

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	11-23-15										
PROPERTY ADDRESS:	2208 BARN	HILL									
PROPERTY OWNER:	KATHERINE D ELROD										
						•					
OCCUPIED: YES NO X	K										
BUILDING ELEMENT	1	CONDIT	ION	NOTES & COMMENTS							
-	VERY				VERY						
	POOR				GOOD						
Foundation Type:		2				MOBILE HOME ,PIERS					
Piers		2									
Solid											
Slab											
Front Porch Type:		2				WOOD DECKING AND STEPS ,OLD					
Wood		2				ROTTED NEEDS REPLACED					
Concrete											
Exterior Doors and Windows						SOME BROKEN ,SOME ROTTED					
Type:						NEEDS REPLACED OR REPAIRED					
Wood		2									
Vinyl		_									
Aluminum											
Roof Underlay Type:						WOOD DECKING IS EXPOSED AND					
OSB/ Plywood	1					ROTTED AND NEEDS REPLACED					
1x6											
metal											
Roof Surface Type: Metal	1					SHINGLES ARE MISSING AND OLD					
3-Tab Shingles						,NEEDS REPLACED					
Dimensional Shingles											
Chimney						N/A					
Siding Type:						IN FAIR SHAPE , EXPOSED AT					
Wood Lap						SEAMS AND NEEDS PAINT					
Vinyl											
Masonite			3								
Aluminum											
Fascia and Trim Type						WOOD FACIA IS WEATHERED AND					
Wood		2				ROTTED IF NOT MISSING IN					
Vinyl Coil						PLACES, NEEDS REPLACED					
Interior Doors Type:						DOORS ARE MISSING OR WARPED					
Hollow Wood			3			FROM WATER LEAKING FROM					
Solid Wood						ROOF					

Interior Walls Type						WOOD FRAME WALLS, EXPOSED	)		
Wood Frame			ļ		3	FROM SHEETROCK MISSING,			
Metal Frame			ļ			ROTTED FROM WATER LEAKS			
Sheetrock			ļ						
Stucco			İ						
Ceilings Type:						ROTTED AND MOLDED FROM			
Sheetrock			İ	2		WATER LEAKING FROM ROOF,			
Stucco			İ			NEEDS REPLACED			
Ceiling Tile			ļ						
Flooring Underlay Type:						FLOORS DAMAGED FROM WATE	R		
1x6 center match			İ			LEAKS, NEEDS REPLACED			
OSB			İ		3				
Plywood			İ		3				
Flooring Surfaces Type:						DAMEAGED FROM WATER			
Carpet			İ			LEAKING OR EVEN MISSING IN			
Linoleum			ļ	2		AREAS ,NEEDS REPLACED			
Hard Wood			ļ						
Vinyl		l							
Electrical				2		NOT TO CODE			
Heating				2		NOT TO CODE			
Plumbing				2		NOT TO CODE			
In my opinion, this structure		is	X	is not	Suit	able for human habitation.			
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.				
m my opinion, and success		1.0		10 110 .	* - [ -	and should be considered and should be conside	19.		
E	MEI	RGE	NCY	ACTI	ON IS	WARRANTED: YES X NO			
P	ROP	ERT	YW	AS SEC	CUREI	O AT TIME OF INSPECTION			
Tim Danaham Chief Duilding	T	-4	_			Other Signature			
Tim Renshaw, Chief Building	ctor	+			Other Signature				
Jing Lense									
			$\dashv$						
Municipal Bui	lding,	, 300	South	Church	Jonesb	oro, Ar./ Phone 870-336-7194/ Fax 870-336-1358			