

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4-24-15	
PROPERTY ADDRESS:	410 E. Gordon	
PROPERTY OWNER:	Douglas Powell - Holvey + Neoma Wille	ams
	•	

BUILDING ELEMENT	1 1	hru 5 C	CONDIT	ION		NOTES & COMMENTS		
	VERY POOR				VERY GOOD			
Foundation Type: Piers Solid Slab		4			e 4	Floor joist is off its piers in several are and falling		
Front Porch Type: Wood Concrete			3			Needs to be replaced		
Exterior Doors and Windows Type: Wood Vinyl Aluminum	-	4				Wood rotted around windows and need to be replaced, some are boarded up		
Roof Underlay Type: OSB/ Plwood 1x6 metal	-	4				Roof is bad in several areas, needs to be replace or repaired		
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles		4				Roof is bad in several areas, needs to be replace or repaired		
Chimney Siding Type: Wood Lap Vinyl Masonite Aluminum		4				Weathered and rotted in several areas and needs to be replaced		
Fascia and Trim Type Wood Vinyl Coil		4		,		Weathered and rotted in several areas and needs to be replaced		
Interior Doors Type: Hollow Wood Solid Wood		4				Most will not close due to settling of floors, some have been removed and need to be replaced		

Interior Walls Type								Need	ds patched and painted	
Wood Frame			,		3				1	
Metal Frame			,							
Sheetrock			1	4			10			
Stucco	14.									
Ceilings Type:								Need	ds patched and painted	
Sheetrock			1		3				-	
Stucco			1				**.			
Ceiling Tile										
Flooring Underlay Type:									or joist is off its piers in several areas	
1x6 center match			1	4				and	falling	
OSB			1			7			-	
Plywood										
Flooring Surfaces Type:									ering has been removed in most	
Carpet			1	4			¥		s and needs to be replaced after	
Linoleum			1				, "	unde	erlay is repaired	
Hard Wood			1							
Vinyl										
	Electrical		5						to code	
Heating			5			Not to code				
Plumbing			5					Not	to code	
		<u> </u>	T		T			⊥		
In my opinion, this structure	-	is	X	is not	Suit	Suitable for human habitation.				
In my opinion this structure		is	X	is not	Phys	Physically feasible for rehabilitation.				
In my opinion, this structure		is	X	is not	Eco	Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not	A pr	A public safety hazard and should be condemned immediately.				
									· .	
EMERGENCY ACTION IS WARRANTED: YES XX NO										
	7,					-				
Tim Renshaw, Chief Building Inspector									Other Signature	
7_11				-						
			1 2	1						

Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358