

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	3-6-17											
PROPERTY ADDRESS:	208 MAPLE	2										
PROPERTY OWNER:	RONALD L WHITE JR.											
OCCUPIED: YES NO	X											
BUILDING ELEMENT	1	thru 5 (CONDIT	ION		NOTES & COMMENTS						
	VERY POOR				VERY GOOD							
Foundation Type: Piers Solid	POOR		3		GOOD	PIERS NEED REPAIRED IN SEVERAL AREAS						
Slab Front Porch Type: Wood Concrete				4		CONCRETE IN FAIR SHAPE						
Exterior Doors and Windows Type: Wood Vinyl Aluminum		2				WOOD WINDOW FRAMES NEED REPLACED OR REPAIRED						
Roof Underlay Type: OSB/ Plywood 1x6 metal		2				OSB OR PLYWOOD NEEDS REPLACED OR REPAIRED IN SEVERAL AREAS						
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles		2				OLD AND NEED REPLACED						
Chimney Siding Type: Wood Lap Vinyl Masonite Aluminum		2				N/A WOOD AND MASONITE , NEEDS REPLACED ALL OVER, ROTTED AND PAINT PEELING						
Fascia and Trim Type Wood Vinyl Coil		2				SAME AS SIDING						
Interior Doors Type: Hollow Wood Solid Wood		2				HOLLOW DOORS NEED REPLACED						

Interior Walls Type								CHEI	ET ROCK AND PANELING,		
Wood Frame				2					ET ROCK AND FANELING, ER DAMAGED AND NEEDS		
Metal Frame									LACED		
Sheetrock								KEFI	LACED		
Stucco											
								337 A 7	ED DAMACED AND NEEDS		
Ceilings Type:				2					ER DAMAGED AND NEEDS		
Sheetrock								KEPI	LACED		
Stucco											
Ceiling Tile								A T T	TWDEG OF COVERNIC HOLES		
Flooring Underlay Type:				2					TYPES OF COVERING, HOLES		
1x6 center match				2					LOORS FROM WATER		
OSB								DAM	IAGE, NEEDS REPLACED		
Plywood											
Flooring Surfaces Type:				2				SAM	E AS ABOVE		
Carpet				2							
Linoleum											
Hard Wood											
Vinyl											
Electrical				2				NOT	TO CODE		
Heating				2				NOT	TO CODE		
Plumbing				2				NOT	TO CODE		
In my opinion, this structure		is	X	is not	Suitable for human habitation.						
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
in my spanion, and surveure		15	1	10 1100	11174	20110 200	100) 11012012		mouse of consensate minimous sy.		
E	MEI	RGE	ENCY	ACTIO	ON IS	WARI	RANTED	: YES	X NO		
Н	OUS	EW	AS 1	NOT SE	CURE	D AT T	IME OF	INSPE	CTION		
The Develop Clift D. 111	T	-4.							Others S'		
Tim Renshaw, Chief Building						Other Signature					
Tim Kenst											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											