

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## **RESIDENTIAL BUILDING INSPECTION REPORT**

DATE OF INSPECTION:	4-7-17											
PROPERTY ADDRESS:	1020 HOPE											
PROPERTY OWNER:	GARY TOOMBS											
OCCUPIED: YES NO	X											
BUILDING ELEMENT	1	thru 5 (	CONDIT	ION		NOTES & COMMENTS						
	VERY POOR				VERY GOOD							
Foundation Type: Piers Solid		2				PIERS ARE FAILING AND NEED REPAIRED						
Slab Front Porch Type: Wood Concrete		2				WOOD , WEAK AND WEATHERED, NEEDS REPLACED						
Exterior Doors and Windows Type: Wood Vinyl			3			IN FAIR SHAPE FOR THEIR AGE, NEEDS REPLACED						
Aluminum Roof Underlay Type: OSB/ Plywood 1x6 metal		2				IN BAD SHAPE ALL OVER , NEEDS NEW ROOF						
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles Chimney		2				BAD , SOME MISSING ALL OLD NEEDS REPLACED						
Siding Type: Wood Lap Vinyl Masonite Aluminum		2				WOOD LAP , NEEDS REPLACED						
Fascia and Trim Type Wood Vinyl Coil		2				SAME AS SIDING						
Interior Doors Type: Hollow Wood Solid Wood		2				MOST ARE MISSING , OTHERS WIILL NOT CLOSE DUE TO FOUNDATION						

Interior Walls Type				2					OD FRAMED IN BAD SHAPE			
Wood Frame				2				DUE	E TO FOUNDATION			
Metal Frame												
Sheetrock												
Stucco												
Ceilings Type:								ALL	TYPES OF CEILINGS , ALL			
Sheetrock			1					NEE	D TO BE REPLACED DUE TO			
Stucco								WAT	FER DAMAGE			
Ceiling Tile												
Flooring Underlay Type:								NOT	SURE WHAT TYPE , NEEDS			
1x6 center match				2				REP	LACED , FALLING OFF PIERS			
OSB												
Plywood												
Flooring Surfaces Type:								ALL	NEED TO BE REPLACED,			
Carpet			1					WAT	TER DAMAGED			
Linoleum												
Hard Wood												
Vinyl												
Electrical				2				NOT	TTO CODE			
Heating				2				NOT	T TO CODE			
Plumbing				2				NOT	TO CODE			
V												
To many an initial state structures			V		Garit	1.1. f	1	- 1- : 4 - 4 :				
In my opinion, this structure		is	Х	is not	Suitable for human habitation.							
In my opinion this structure		is	Х	is not	Physically feasible for rehabilitation.							
In my opinion, this structure		is	Χ	is not	Economically feasible for rehabilitation.							
In my opinion, this structure	Х	is		is not	A public safety hazard and should be condemned immediately.							
									XX NO			
PRC	PER	TY	WAS	S NOT S	ECUR	ED AT	TIME O	F INSI	PECTION			
Tim Renshaw, Chief Building						Other Signature						
Tim Renol		_										
	1 10	200			r	· · · · · /	DI 070	226 81	194/ Fax 870-336-1358			