

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-7-17				
PROPERTY ADDRESS:	650 W. MONROE				
PROPERTY OWNER:	LINDA LEA BALI				
			,		
OCCUPIED: YES NO	X				
	1 41 5 (CONDITION	NOTES & COMMENTS		
BUILDING ELEMENT	•	CONDITION	NOTES & COMMENTS		
	VERY POOR	VERY GOOD			
Foundation Type:			FLOOR JOIST ARE OFF PIERS,		
Piers	2		NEEDS REPAIRED		
Solid					
Slab					
Front Porch Type:			HAS HOLES AND WHEATHERED,		
Wood	2		NEEDS REPLACED		
Concrete					
Exterior Doors and Windows			SOME ARE MISSING AND BOADED		
Type:			UP, ALL NEED RERPLACED		
Wood	2				
Vinyl					
Aluminum					
Roof Underlay Type:			OLD AND FAILING ALL OVER		
OSB/ Plywood	2		NEEDS REPLACED		
1x6					
metal					
Roof Surface Type: Metal			THREE TAB SHINGLES IN BAD		
3-Tab Shingles	2		SHAPE, ALL NEED REPLACED		
Dimensional Shingles					
Chimney					
Siding Type:			VINAL AND ALUMINUM		
Wood Lap			DAMAGED AND MISSING IN		
Vinyl			AREAS , NEEDS REPLACED		
Masonite					
Aluminum					
Fascia and Trim Type			ROTTED IN SEVERAL AREAS,		
Wood	2		NEEDS REPLACED		
Vinyl Coil					
Interior Doors Type:			CAN'T USE DUE TO SHIFTING OF		
Hollow Wood	2		THE FLOORS, NEEDS REPLACED		
Solid Wood					

Interior Walls Type	I		ŀ		i İ	SHEETROCK AND STUCCO, HOI	LES			
Wood Frame	I		ŀ	2	i İ	IN WALLS AND CRACKS				
Metal Frame	I		ŀ		i	THROUGHOUT DUE TO SHIFTIN	(G			
Sheetrock	I		ŀ		i	OF THE FLOORS				
Stucco		<u> </u>			ļ					
Ceilings Type:	I		ŀ		i	SHEETROCK WATER DAMAGED				
Sheetrock	I		ŀ	2	i	THROUGHOUT, NEEDS REPLACE	ED			
Stucco	I		I			,				
Ceiling Tile		<u> </u>			ļ					
Flooring Underlay Type:	I		ŀ		i İ	OSB OR PLYWOOD IN BAD SHAI	PE			
1x6 center match	I		ŀ	2	i İ	NEEDS REPLACED				
OSB	I		ŀ		i	,				
Plywood		l	'		i					
Flooring Surfaces Type:						ALL TYPES OF COVERINGS ,ALI	L			
Carpet	I		I			NEED TO BE REPLACED				
Linoleum	I		ŀ	2	i İ	,				
Hard Wood	I		ŀ		i	,				
Vinyl	I		ŀ		i	,				
Electrical				2		NOT TO CODE				
Heating				2		NOT TO CODE				
Plumbing				2		NOT TO CODE				
	-									
In my opinion, this structure		is	X	is not	Suita	able for human habitation.				
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.					
In my opinion, this structure	X	is		is not	Ecor	Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not	A pt	A public safety hazard and should be condemned immediately.				
			,			<u> </u>				
E	MEF	RGE	NCY	ACTI	ON IS	WARRANTED: YES X NO				
HON	ME V	WAS	3 NO	T SECU	JRED /	AT THE TIME OF INSPECTION				
			'							
Tim Renshaw, Chief Building Inspector						Other Signature				
Tim Renol										
			+	 						
			+							
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358										