

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-19-17											
PROPERTY ADDRESS:	2420 DUDLEY											
PROPERTY OWNER:	LINDY HOLDINGS LLC											
OCCUPIED: YES NO	K											
BUILDING ELEMENT	1	thru 5 (CONDIT	ION		NOTES & COMMENTS						
	VERY	1		VERY								
	POOR				GOOD							
Foundation Type:			3			PIERS, SEEMED TO BE IN GOOD						
Piers						,FAIR ,SHAPE						
Solid												
Slab												
Front Porch Type:			3			CONCRETE STEPS						
Wood												
Concrete												
Exterior Doors and Windows	1					MOST WINDOWS ARE MISSING,						
Type:						ALL NEED TO BE REPLACED						
Wood												
Vinyl												
Aluminum												
Roof Underlay Type:						1X6 IN FAIR SHAPE EXCEPT IN						
OSB/ Plywood						BURNED AREAS						
1x6		2										
metal		2										
Roof Surface Type: Metal						ALL SHINGLES NEED TO BE						
3-Tab Shingles		2				REPLACED						
Dimensional Shingles												
Chimney						N/A						
Siding Type:			3			LAP MASONITE AND BRICK HALF						
Wood Lap						WAY, REPAIRS NEEDED						
Vinyl												
Masonite												
Aluminum												
Fascia and Trim Type		2				ROTTED AND MISSING IN SOME						
Wood						AREAS, ALL NEED REPLACED OR						
Vinyl Coil						REPAIRED						
Interior Doors Type:		2				ALL NEED REPLACED OR						
Hollow Wood						REPAIRED						
Solid Wood												

Interior Walls Type Wood Frame				2					PANELING NEEDS REPLACED REPAIRED , PEELING AND		
Metal Frame									TER DAMAGED		
Sheetrock								,,,,,,			
Stucco											
Ceilings Type:								NO C	CEILING THROUGHOUT, MUST		
Sheetrock								BE R	EPLACED		
Stucco											
Ceiling Tile			1								
Flooring Underlay Type:								OSB	AND PLYWOOD WATER		
1x6 center match								DAM	IAGED,NEEDS REPLACED		
OSB				2							
Plywood											
Flooring Surfaces Type:								NEE	DS REPLACED THROUGHOUT ,		
Carpet			1								
Linoleum			1								
Hard Wood											
Vinyl											
Electrical			1					NOT	TO CODE		
Heating		1						NOT	TO CODE		
Plumbing		1						NOT	TO CODE		
					1						
In my opinion, this structure		is	X	is not	Suitable for human habitation.						
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
	X	is		is not	A public safety hazard and should be condemned immediately.						
							RANTEL				
PR	OPEI	KTY	WA	S NOT S	SECUF	RED AT	TIME C	OF INS	PECTION		
Tim Renshaw, Chief Building Inspector									Other Signature		
Tim Lense											
Municipal Du	ildina	300	South	Church	Ionach	no An /	Dhone 970	336 71	94/ Fax 870-336-1358		
Municipal Bu	numg	, 500	South	i Church	JOHESD(πυ, Аг./	r none 8/0	-330-/1	74/ Fax 0/U-33U-1330		