

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-12-17							
PROPERTY ADDRESS:	4006 E HIG							
PROPERTY OWNER:	KEVIN K K							
OCCUPIED: YES X NO)							
BUILDING ELEMENT	1	thru 5 (CONDIT	ION		NOTES & COMMENTS		
DOLEDING BEENENI	VERY	T T	1	1	VERY	TOTES & COMMENTS		
	POOR				GOOD			
Foundation Type:		2				PIERS, HOUSE FALLING OFF PIERS,		
Piers						FLOORS SAGGING THROUGHOUT		
Solid								
Slab								
Front Porch Type:			3			WOOD PORCH IN FAIR SHAPE		
Wood								
Concrete								
Exterior Doors and Windows			3			SOME WINDOWS ARE MISSING ,		
Type:						MOST ARE 4UNDER SIZED AND		
Wood						FRAMED AROUND WITHOUT		
Vinyl						COVERINGS		
Aluminum								
Roof Underlay Type:		2				APPEARS TO BE PLYWOOD WITH		
OSB/ Plywood						SAGGING ALL OVER , NEEDS		
1x6						REPLACED		
metal								
Roof Surface Type: Metal		2				HAVE BEEEN PATCHED ALL OVER		
3-Tab Shingles						, REAR OF HOUSE IN WORSE		
Dimensional Shingles						SHAPE THAN FRONT, NEEDS		
						REPLACED		
Chimney						N/A		
Siding Type:		2				NEEDS REPLACED, VINYL IN BAD		
Wood Lap						SHAPE		
Vinyl								
Masonite								
Aluminum								
		2				MOGERIA CIA IGA MICADIO AND		
Facia an trim		2				MOST FACIA IS MISSING AND		
						ROTTED ,NEEDS REPLACED ,		
						VINYL TRIM IN SAME SHAPE		
			1	1	1			

Interior Walls Type				2					missing and will not close or open due to		
Wood Frame								settlin	g of floors		
Metal Frame											
Sheetrock											
Stucco											
Ceilings Type:					3			SHE	ETROCK , DAMAGED DUE TO		
Sheetrock								WAT	TER LEAKS, NEEDS REPAIRED		
Stucco								OR F	REPLACED		
Ceiling Tile											
Flooring Underlay Type:				2				OSB	DAMAGED IN KITCHEN AND		
1x6 center match								BAT	HROOM DUE TO WATER		
OSB								DAM	IAGE		
Plywood											
Flooring Surfaces Type:				2				NEE	DS REPLACED OR REPAIRED		
Carpet								FRO	M WATER DAMAGE, CARPET		
Linoleum									TILE		
Hard Wood											
Vinyl											
Electrical					3			NOT	TO CODE		
Heating					3			NOT	TO CODE		
Plumbing					3			NEE	DS REPAIRS		
Č											
In my opinion, this structure		is	X	is not	Suitable for human habitation.				on.		
In my opinion this structure	X	is		is not	Physically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
	1 M AFT	OCE	NICE	7 A CUEDE 4	NI TO	XX/ADD	ANIME	375 0	LW NO		
							ANTED				
DUE TO THE NATUR	E OF	TH	E US	E OF TH	њ нО	ME, E	MEKGE	NCY A	CTION IS WARRANTED		
Tim Renshaw, Chief Building Inspector									Other Signature		
Times Lenston											
1											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											