

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-24-15										
PROPERTY ADDRESS:	502 Parkview Shirley A. Kuster										
PROPERTY OWNER:											
					***************************************						
OCCUPIED: YES NO	XX		000000000000000000000000000000000000000								
BUILDING ELEMENT	1 1 t	hru 5 CC	ONDITI	ON	NOTES & COMMENTS						
	VERY POOR				VERY GOOD	·					
Foundation Type: Piers Solid Slab	Took					House Completely destroyed by fire					
Front Porch Type: Wood Concrete						House Completely destroyed by fire					
Exterior Doors and Windows Type: Wood Vinyl Aluminum					•	House Completely destroyed by fire					
Roof Underlay Type: OSB/ Plwood 1x6 metal						House Completely destroyed by fire					
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles Chimney					•	House Completely destroyed by fire					
Siding Type: Wood Lap Vinyl Masonite Aluminum						House Completely destroyed by fire					
Fascia and Trim Type Wood Vinyl Coil						House Completely destroyed by fire					
Interior Doors Type: Hollow Wood Solid Wood	* *					House Completely destroyed by fire					

Interior Walls Type	)							House Completely destroyed by fire		
Wood Frame				000000000000000000000000000000000000000				Trouse completely destroyed by file		
Metal Frame						appropriate and the second				
Sheetrock				/						
Stucco										
								House Completely destroyed by fire		
Ceilings Type:								House Completely destroyed by file		
Sheetrock							•			
Stucco		-								
Ceiling Tile								II. C. let let let en la Con		
Flooring Underlay Type:								House Completely destroyed by fire		
1x6 center match										
OSB								*		
Plywood	<u> </u>					-		2 2 2		
Flooring Surfaces Type:				· ·						
Carpet		200000000000000000000000000000000000000		Bananana Banana Bana			4	House Completely destroyed by fire		
Linoleum										
Hard Wood								*		
Vinyl										
Electrical							,	Not to code		
Heating								Not to code		
Plumbing								Not to code		
In my opinion, this structure		is	XX	is not	Suitable for human habitation.					
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.					
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.					
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned					
in my opinion, this structure	AA	15		15 1101		nediatel		id and should be condemiced		
	1			1	111111	iculatel	J.	•		
TF)	MED	CEN	CV A	CTION	TS W	ARDA	NTFD.	YES XX NO		
		******	***************************************					NSPECTION		
	***************************************		Total Control of the	*						
Tim Renshaw, Chief Building Inspector							*	Other Signature		
							**************************************			
Municipal Bu	ilding	300	South (	Church J	nesbo	ro, Ar./)	Phone 870-	336-7194/ Fax 870-336-1358		