

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:   2-2	25-2014				
PROPERTY ADDRESS: 81	5 Mays R	d			
PROPERTY OWNER: De	eutsche Ba	nk Natio	nal Trust (	Co.	
					· · · · · · · · · · · · · · · · · · ·
OCCUPIED: YES xx N	O				
BUILDING ELEMENT	1	thru 5 CO	NDITION		NOTES & COMMENTS
	VERY POOR			VERY GOOD	
Foundation Type:	TOOK	2		GOOD	Poor condition showing signs of
Piers		2			dilapidation
Solid			n		1
Slab					
Front Porch Type:				5	Concrete porch in goo condition
Wood					
Concrete					
Exterior Doors and Windows		2			Broke but secure for now
Type:Doors: Metal					
Wood					
Vinyl					
Aluminum					
Roof Underlay Type:	1				Rotten and falling due to roof leaks
OSB/ Plywood:					
1x6					
metal					
Roof Surface Type:	1				Rotten/ dilapidated and leaking
3-Tab Shingles					causing damage to inside
Dimensional Shingles					
Chimney					N/A
Siding Type:	1				Rotten/dilapidated and falling of
Wood Lap					
Vinyl					
Masonite/ Lap					
Aluminum					
Fascia and Trim Type	1				Rotten/dilapidated and falling off
Wood					
Vinyl Coil	-				
Interior Doors Type:		2			Could not access looked at through
Hollow Wood					windows/ poor condition
Solid Wood	II .	1	1	1	T .

g Insp			<u> </u>	D 4 F' W 1 1				
	-			Craig Davenport, Fire Marshal Other Signature				
EKG	LIN	CYA	CHON	IS WARRANTED: YES xx NO				
				to be abated/ Strucutre shows severe signs of dilapidation				
XX			immediately.					
	is	XX	is not	Economically feasible for rehabilitation.				
	is	xx	is not	Physically feasible for rehabilitation.				
	is	XX	is not	Suitable for human habitation.				
	-							
	-	1		Not to code				
	-			Not to code				
		1		Not to code				
				would be suspect for dilapidation				
		1		Due to leaking roof floor covering would be suspect for dilapidation				
	-	1		Don't lasting and Community				
		1		Rotten due to roof leaks				
			-					
		•		raining in due to foot leak				
	+	1		Falling in due to roof leak				
				ceiling and bearing walls				
				walls are already separated from				
				suspect of rotten and collapsing. So				
	re th	is is xx is	is xx  is xx  xx is   ure the structu	1				