



Photo 15 - North exterior wall. Broken glass block.



Photo 16 - North exterior wall. Fallen bricks from parapet.




Photo 17 - North exterior wall.



Photo 18- East exterior wall. Brick not original, or has been pointed with cement mortar. Fire blackening on parapet.



Photo 19- East exterior wall. Brick not original, or has been pointed with cement mortar. Fire blackening on parapet.




Photo 20- East exterior wall. Brick not original, or has been pointed with cement mortar. Fire blackening on parapet.



Photo 21 - East exterior wall. Brick not original, or has been pointed with cement mortar. Brick is stacked and not properly bonded with mortared or not tied with soldier course.



Photo 22 - stair well to 'Loft'. Water soaked gypsum board.



Photo 23 - Ceiling in stairwell. Gypsum board and insulation water soaked






Photo 24 - Ceiling in stairwell. Gypsum board and insulation water soaked



Photo 25 - Ceiling in stairwell. Gypsum board and insulation water soaked



Photo 26 - Loft looking south. Ceiling consumed by fire and collapsed onto floor. Windows look into light well formed by adjoining building.