

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION: 11-	26-2013											
PROPERTY ADDRESS: 804 Chestnut												
PROPERTY OWNER: Rickey L. Bradsher												
TROTERTTOWNER.	Rey L. Diadonei											
OCCUPIED: YES XX NO)											
Geeches. Lie in it.												
BUILDING ELEMENT	1 thru 5 C	CONDITION	NOTES & COMMENTS									
	VERY POOR	VER GOO										
Foundation Type:	1		Completely Dilapidated									
Piers												
Solid												
Slab												
Front Porch Type:	1		Non-Existing									
Wood												
Concrete												
Exterior Doors and Windows	1		Rotten Broke and Busted									
Type												
Wood												
Vinyl												
Aluminum												
Roof Underlay Type: Plywood	1		Rotten Leaking									
OSB												
1x6												
metal												
Roof Surface Type:	1		Rotten leaking into structure approx.									
3-Tab Shingles			12-15 yrs. old									
Dimensional Shingles												
Chimney	1		N/A									
Siding Type:	1		Rotten deterioated									
Wood Lap												
Vinyl												
Masonite												
Aluminum												
Fascia and Trim Type	1		Rotten falling off									
Wood												
Vinyl Coil												
Interior Doors Type:			Could not access									
Hollow Wood												

Solid Wood											
Interior Walls Type								Coı	ıld	not access	
Wood Frame											
Metal Frame											
Sheetrock								=			
Stucco							5 5				
Ceilings Type:								Col	114	not access	
Sheetrock								Col	uiu	not access	
Stucco							7,0				
							5				
Ceiling Tile								Car	.1.1	not access	
Flooring Underlay Type:								Col	ura	not access	
1x6 center match											
OSB								2,			
Plywood								-	1 1		
Flooring Surfaces Type:							- % J.	Coi	uld	not access	
Carpet											
Linoleum							·				
Hard Wood											
Vinyl											
Electrical			1					Not to code			
Heating	1								Not to code		
Plumbing	1		1		Y			Not	Not to code		
In my opinion, this		is	XX	is not	Suitable for human habitation.						
structure											
In my opinion this		is	XX	is not	Phys	Physically feasible for rehabilitation.					
structure		13	AA	15 HOT	I my.	I hysically leasible for renabilitation.					
structure											
In my opinion, this		is	XX	is not	Economically feasible for rehabilitation.						
structure											
In my opinion, this	XX	is		is not	t A public safety hazard and should be condemned						
structure	AA	13		15 Hot	immediately.						
Due to safety, health and we	lfare	ctri	leutr	e needs			<i>J</i> ·				
				CTION			NTED.	$\neg \mathbf{v}$	ES	xx NO	
15141	LICO	EIV	CIA	CTIO	115 11	AICICA	MIED.			AATTO	
1 LA									П		
Terry Adams, Certified Building Inspector				Craig Davenport, Fire Marshal Other Signature					Other Signature		
Terry Adams, Certified Building Inspector				Craig Davenport, Fire marshar Other Signature					July Digmedit		
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											