

AFFIDAVIT	
Patricia Hanks	
C10 Paul + Cherrie Kassen	
2020 N Church St.	
Jonesboro, AR 72401	
RE: 2034 N Church Jonesboro, AV	C 72401
I, Michael McQuay, a Code Enforcement Officer, being duly sworn upon o	oath, that I served the
attached notice(s) upon each of the persons or firms therein addressed, by o	
thereof in the United States Mail, enclosed within envelopes plainly address	
postage fully prepaid, at the Jonesboro, Arkansas Post Office located at 310) East Street, Suite A.,
before 3:00 P.M., on the 15+ day of September, 2022	<u>L</u> .
Michael McQuay	7
Jonesboro Code Enforce	cement
Subscribed and sworn to before me the 1st day of September	<u>, 2022</u> .
Shan Motato Notary Public	MINION MCINTOSAMILLE CONTROL PUBLIC
	ARKANSAS

My commission expires: May 20, 2032



Notice of Violation

Date: 09/01/2022

PATRICIA HANKS C/O PAUL & CHERRIE KASSEN 2020 N CHURCH ST JONESBORO, AR 72401

SUBJECT: 2034 N CHURCH JONESBORO, AR 72401

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley Code Enforcement Officer P.O. Box 1845

Jonesboro, AR 72403

CE22-1664

Sign if served in person



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

BUILDING INSPECTION REPORT

DATE OF INSPECTION:	SEPTEMBER 1, 2022		CAS	CASE NUMBER: CE22-1664			
PROPERTY ADDRESS:	2034 N. CHURCH						
			tenucia voneza				
PROPERTY OWNER:			ANKS	C/O P	PAUL	& CHER	RRIE KASSEN
	O XX			0115			1
BUILDING ELEMENT		1 thru 5 CONDITION				NOTES & COMMENTS	
		VERY POOR				VERY GOOD	
Foundation Type:				3			SLAB FOUDATION IN FAIR
Piers							CONDITION
Solid							
Slab							
Front Porch Type:				3			CONCRETE IN FAIR
Wood							CONDITION
Concrete							
Exterior Doors and Windov	VS	1					MOST ARE BROKEN OR
Type:	2000						BOARDED, ALL NEED
Wood							REPLACED.
Vinyl							
Aluminum							
Roof Underlay Type:		1					UNDERLAY IS SAGGING, FALLING
OSB/ Plywood							IN, OR MISSING. ALL NEEDS
1x6							REPLACED. ROOF COMPLETELY
metal							GONE ON BACK OF BUILDING.
Roof Surface Type: Metal		1					METAL ROOF IS BENT,
3-Tab Shingles							SEPARATED IN VERY POOR
Dimensional Shingles							CONDITION
Chimney							N/A
Siding Type:					4		STONE EXTERIOR. NO MAJOR
Wood Lap							ISSUES
Vinyl							
Masonite							
Aluminum							
Fascia and Trim Type		1					FASICIA AND TRIM ARE
Wood							ROTTEN AND FALLING OFF.
Vinyl Coil							NEEDS REPLACED
Interior Doors Type:			2				BROKEN OR MISSING. ALL
Hollow Wood							NEED REPLACED
Solid Wood							
Interior Walls Type		1					SHEETROCK WALLS WITH
Wood Frame							HOLES, AND WATER DAMAGE
Metal Frame							THROUGHOUT. STUDS
Sheetrock							EXPOSED IN BACK OF
Stucco							BUILDING. ALL SHEETROCK REPLACED

Ceilings Type:			1		SHEETROCK CEILINGS.		
Sheetrock Stucco					HOLES, MISSING, AND		
Ceiling Tile					WATER DAMAGE		
P					THROUGHOUT. ALL NEEDS REPLACED		
Flooring Underlay Type:					EXPOSED SLAB		
1x6 center match							
OSB							
Plywood			,				
	Flooring Surfaces Type:		1		MOSTLY MISSING OR		
Carpet					WATER DAMAGED IN PARTS		
Linoleum					ACCESSABLE		
Hard Wood							
Vinyl							
Electrical			1		NOT TO CODE. EXPOSED		
					WIRES		
Heating			1		NOT TO CODE.		
Plumbing			1		NOT TO CODE. ACTIVE		
					LEAKS		
In my opinion, this		is	XX	is not	Suitable for human habitation.		
structure							
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.		
In my opinion, this		is	XX	is not	Economically feasible for rehabilitation.		
structure structure		13	AA	15 1101	Economicany leastore for renadmation.		
In my opinion, this	XX	is		is not	A public safety hazard and should be condemned		
structure					immediately.		
EM	ERGE	NC	V AC'	TION IS	WARRANTED: YES NO XX		
					AT TIME OF INSPECTION.		
Tim Renshaw, Chief Building Inspector				David Cooley, Code Enforcement			
Tim Lenolm				200			
Municipal Build	ling, 30	0 Soi	uth Chu	rch Jone	boro, Ar./ Phone 870-336-7194/ Fax 870-336-1358		

