


My commission expires: _

AFFIDAVIT
Gateway Mortgage Group LLC
244 5 Gateway Pl.
Jenks, OK 74037
RE: 309 Mockingbird CV APN #01-144303-28100 Janes boro, AR 7240
Jones boro, AR 7240
I, Michael McQuay, a Code Enforcement Officer, being duly sworn upon oath, that I served the
attached notice(s) upon each of the persons or firms therein addressed, by depositing copies
thereof in the United States Mail, enclosed within envelopes plainly addressed, as shown with
postage fully prepaid, at the Jonesboro, Arkansas Post Office located at 310 East Street, Suite A.,
before 3:00 P.M., on the 5 day of August, 2027.
much lay 10 m
Michael McQuay Jonesboro Code Enforcement
Subscribed and sworn to before me the 10th day of August, 2022.
Notary Public ARKANSAS

May 20, 2032



Notice of Violation

Date: 08/03/2022

GATEWAY MORTGAGE GROUP LLC 244 S GATEWAY PL

JENKS, OK 74037 Work: 501-777-3580

SUBJECT: 309 MOCKINGBIRD CV

JONESBORO, AR 72401

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley Code Enforcement Officer

P.O. Box 1845 Jonesboro, AR 72403

CE22-6

Sign if served in person

Code Enforcement Officer Signature, if delivered in person

Property Owner/Interested Party Signature, if delivered in person



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

- N														
DATE OF INSPECTION:	AUG	UST 3, 2	022		CASE NUMBER: CE22-6									
COLUMN ACTION OF THE PROPERTY	200 7	10 CT 177												
PROPERTY ADDRESS: 309 MOCKINGBIRD CV. PARCEL # 01-144303-28100														
PROPERTY OWNER:	GAT	EWAY N	MORT	GAGE	GRO	UP LLC								
OCCUPIED. VEG. NO.	3737													
	DIVI DIVIC W PLANTE													
BUILDING ELEMENT			iru 5 C	ONDIT	ION		NOTES & COMMENTS							
		VERY POOR				VERY GOOD								
Foundation Type:				3		GOOD	HOME IS ON PIER							
Piers							FOUNDATION, GARAGE IS							
Solid							ON SLAB. BOTH ARE IN FAIR							
Slab							CONDITION.							
Front Porch Type:				3			CONCRETE IN FAIR SHAPE							
Wood							CONCRETE IN TAIR SHALE							
Concrete														
Exterior Doors and Window	'S			3			MOST ARE INTACT.							
Type:							ALTHOUGH THE HOME WAS							
Wood							NOT SECURED AT THE TIME							
Vinyl							OF INSPECTION.							
Aluminum							OF INSPECTION.							
Roof Underlay Type:		1			-		ROOF IS SAGGING AND							
OSB/ Plywood		•					LEAKING. ALL UNDERLAY							
1x6														
metal							NEEDS REPLACED.							
Roof Surface Type: Metal		1					CHINCLES ARE OLD							
3-Tab Shingles		1					SHINGLES ARE OLD,							
Dimensional Shingles							DAMAGED, AND LEAK.							
Chimney					4		MUST BE REPLACED							
Siding Type:	-			3	4		NO ISSUES VISABLE.							
Wood Lap				3			SIDING IS IN FAIR SHAPE.							
Vinyl							SOME PLACES NEED							
Masonite							REPAIRED OR REPLACED.							
Aluminum														
				3			7.000							
Fascia and Trim Type				3			FASICIA AND TRIM ARE IN							
Wood							FAIR SHAPE. SOME PLACES							
Vinyl Coil							NEED REPAIRED OR							
							REPLACED.							
Interior Doors Type:			2				MANY WADDED DITE TO THE							
Hollow Wood			4				MANY WARPED DUE TO THE							
Solid Wood							MOISTURE FROM THE ROOF							
Solid Wood							LEAKS AND NEED							
							REPLACED.							

Interior Walls Type			1					SHEETROCK SOME WITH		
Wood Frame								WATER DAMAGE AND		
Metal Frame								EVIDENCE OF MOLD AND		
Sheetrock								MILDEW. NEEDS REPLACED		
Stucco								AND FRAME TREATED TO		
proved an acceptance to the control of the control		1		1 1				KILL MOLD GROWTH.		
				1 1				KILL MOLD GROW III.		
Ceilings Type:			1					SHEETROCK SOME WITH		
Sheetrock								WATER DAMAGE AND		
Stucco								EVIDENCE OF MOLD AND		
Ceiling Tile										
cening the								MILDEW. NEEDS REPLACED		
								AND FRAME TREATED TO		
								KILL MOLD GROWTH.		
Flooring Underlay Type:				2				PLYWOOD UNDERLAY		
1x6 center match	Š			2				NEEDS REPLACED, SHOWS		
OSB										
Plywood								EVIDENCE OF WATER		
			4					DAMAGE.		
Flooring Surfaces Type:			1			- 0		ALL FLOOR COVERING		
Carpet								NEEDS REPLACED. DUE TO		
Linoleum								THE ROOF LEAK IT IS		
Hard Wood								WAVING AND COMING UP		
Vinyl								FROM THE UNDERLAY.		
Electrical								ACTIVE		
Heating								ACTIVE		
Plumbing								ACTIVE		
In my opinion, this	T	is	XX	is not	Suit	able fo	or human	habitation.		
structure										
In my opinion this	XX	is		is not	Phy	sically	feasible	for rehabilitation.		
structure				15 1101	1 11	orearry	Tousion	ioi ionaomation.		
In my opinion, this	XX	is		ianot	Eggs		aller famail	ala fan arkakilitati		
structure	AA	15		is not	Eco	nomic	any reasn	ble for rehabilitation.		
In my opinion, this	XX	is		is not	A public safety hazard and should be condemned					
structure					imm	ediate	ely.			
			**							
HOME WAS NOT SEC	MERGE	INC	YAC	TION IS	S WA	RRAN	NTED: Y	YES NO XX		
HOME WAS NOT SECU	URE AT	111	ME OF	INSPE	CTIO	N.				
Tim Renshaw, Chief Build	ling Inspe	ector						David Cooley, Code Enforcement		
Zin Zen						7	-	197		
								- 27		
Municipal Bui	ilding 30	n Sa	uth Chr	reh Ioro	choro	An / Di	1000 970 2	36-7194/ Fax 870-336-1358		
iviunicipal bui	numg, 30	0 30	utii Cilt	ii ch Johe	souru,	Ar./ PI	10116 6/0-3.	30-/174/ Fax 8/0-330-1338		

CERTIFIED MAIL® RECEIPT

Domestic Mail Only

For delivery information, visit our website at www.usps.com*.

Certified Mail Fee

Extra Services & Fees (check box, add fee as appliants)

Return Receipt (sectionic)

Return Receipt (electronic)

Adult Signature Receipt delivery \$

Adult Signature Receipt delivery \$

Postage

Total Postage and Fees

Sent To at evan Mortgase Group LV

Sitest and Apr. No., or PO By No.

City, State, 219-11

PS Form 3800, April 2015 SN 7553-02-200-2647

See Reverse for Instructions