

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-10-16													
PROPERTY ADDRESS:	1403 OAKHURST													
PROPERTY OWNER: A+ PROPERTY MANAGEMENT														
OCCUPIED: YES NO X														
BUILDING ELEMENT	1 -	thru 5 (CONDIT	ION		NOTES & COMMENTS								
Belebii (G EEE/IEI (T	VERY	unus	JONE	1011	VERY	THOTES & COMMENTS								
	POOR				GOOD									
Foundation Type:			_			HOUSE ON PIERS NEEDS LEVELED								
Piers			3			AND REPAIRED								
Solid														
Slab														
Front Porch Type:						CONCRETE PORCH, NEEDS								
Wood			2			REPAIRS								
Concrete			3											
Exterior Doors and Windows						MOST WINDOWS ARE MISSING OR								
Type:		2				BOARDED UP								
Wood		2												
Vinyl														
Aluminum														
Roof Underlay Type:						UNDERLAY APPEARS TO BE IN								
OSB/ Plywood			3			NEED OF REPLACEMENT,								
1x6						SAGGING IN AREAS								
metal														
Roof Surface Type: Metal						THREE OR MORE LAYERS ,IN								
3-Tab Shingles		2				NEED OF REPLACEMENT								
Dimensional Shingles														
Chimney						N/A								
Siding Type:						OLD WOODEN SIDING IS BROKEN								
Wood Lap	1					AND MISSING ALL OVER, NEEDS								
Vinyl	1					REPLACED								
Masonite														
Aluminum														
Fascia and Trim Type						OLD ROTTED WOOD NEEDS								
Wood		2				REPLACED								
Vinyl Coil														
Interior Doors Type:						N/A NEEDS REPLACED								
Hollow Wood		2												
Solid Wood			<u> </u>											

				1		1		1				
Interior Walls Type									D STUD FRAME EXPOSED			
Wood Frame				2				FROM	1 LACK OF WALL COVERING			
Metal Frame												
Sheetrock												
Stucco												
Ceilings Type:								SHEE	TROCK NEEDS REPAIRED OR			
Sheetrock					3			REPL	ACED			
Stucco												
Ceiling Tile												
Flooring Underlay Type:									TLE OF EVERYTHING , NEEDS			
1x6 center match				2					ACED OR REPAIRED, SOME			
OSB								JOIST	AND ALL IS MISSING			
Plywood								<u> </u>				
Flooring Surfaces Type:									LOOR COVERING THROUGH			
Carpet			1					THE I	HOUSE			
Linoleum												
Hard Wood												
Vinyl												
Electrical			1					NOT '	TO CODE			
Heating		1						NOT '	TO CODE			
Plumbing		1						NOT '	TO CODE			
		Γ						T				
In my opinion, this structure	- -	is	X	is not	Suita	able for	human h	abitatio	n.			
In my opinion this structure	X	is		is not	Physically feasible for rehabilitation.							
In my opinion, this structure		is	X	is not	Eco	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A pu	A public safety hazard and should be condemned immediately.						
							RANTED					
H	<u>OUS</u>	E W	'AS N	NOT SE	CURE	D AT I	TIME OF	INSPEC	CTION			
The Development Chief Devilding	T	4 3 24	\perp						Od Chanakana			
Tim Renshaw, Chief Building						Other Signature						
Jim Lenol												
			士									
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358												