

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	8-21-18								
PROPERTY ADDRESS:	1210 HUNTINGTON AVE								
PROPERTY OWNER: STUART GLEN BLALOCK									
OCCUPIED: YES NO									
BUILDING ELEMENT	1	thru 5	CONDITIO	N	NOTES & COMMENTS				
	VERY POOR			VERY GOOD					
Foundation Type: Piers Solid Slab	1000		3	GOOD	PIERS AND SLAB WITH BASEMENT, IN GOOD SHAPE				
Front Porch Type: Wood Concrete			3		CONCRETE PORCH IN FAIR SHAPE				
Exterior Doors and Windows Type: Wood Vinyl Aluminum		2			WOOD DOORS AND WINDOWS, MOST ARE BROKEN AND NEED REPLACED, NONE ARE SECURED				
Roof Underlay Type: OSB/ Plywood 1x6 metal		2			WOOD UNDERLAY IN FAIR SHAPE				
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles		2			THREE TAB SHINGLES IN FAIR SHAPE				
Chimney			3		GOOD SHAPE				
Siding Type: Wood Lap Vinyl Masonite Aluminum		2			BRICK AND VINYL SIDING IN FAIR SHAPE				
Fascia and Trim Type Wood Vinyl Coil			3		VINYL IN FAIR SHAPE				
Interior Doors Type: Hollow Wood		2			WOOD AND GLASS INTERIOR DOORS MOST SRE BROKEN DUE				

TO VANDALS

Solid Wood

Interior Walls Type		\top		T		WOOD TO LACTOR				
Wood Frame				1	3	WOOD FRAMED WALLS APPEAR				
Metal Frame				1		TO BE IN GOOD SHAPE				
Sheetrock										
Stucco				1						
Ceilings Type:		+		-	-	200000000000000000000000000000000000000				
Sheetrock					3	SHEETROCK CEILINGS IN FAIR				
Stucco					1	SHAPE				
Ceiling Tile										
Flooring Underlay Type:		+		+	-					
1x6 center match						WOOD UNDERLAY IN GOOD				
OSB					3	SHAPE				
Plywood										
Flooring Surfaces Type:					2	ALL TYPES OF FLOOR COVERING,				
Carpet					3	SOME WILL NEED TO BE				
Linoleum						REPAIRED AND REPLACED				
Hard Wood										
Vinyl										
Electrical					3	MAY NEED UPGRADES				
Heating					3	MAY NEED REPACED				
Plumbing					3	MAY NEED REPAIRS				
In my opinion, this structure		is	X	is not	Suitab	ble for human habitation.				
In my opinion this structure	X	is		is not	Physic	Physically feasible for rehabilitation.				
In my opinion, this structure		is	X	is not		Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not		A public safety hazard and should be condemned immediately.				
		1		15 110	11 pac-	ne salety hazard and should be condenned infinediately.				
E	MER	GE	NCY	ACTIO	N IS W	ARRANTED: YES XX NO				
H	OUS	E W	ASN	NOT SEC	CURED	AT TIME OF INSPECTION				
Tim Renshaw, Chief Building Inspector						Other Signature				
Jan Sensen										
			+							
			+							
Municipal Bui	lding	, 300	South	Church J	Jonesboro	ro, Ar./ Phone 870-336-7194/ Fax 870-336-1358				
	A STATE OF THE PARTY	100		12 12 12 12 12	A 100 M 100 M					