

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## COMMERCIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	8-9-18											
PROPERTY ADDRESS:	808 WARRI	EN		l								
PROPERTY OWNER:	FAITH SOULS OUTREACH MINISTRIES INC.											
TROTERTT OWNER.	FAITHSOC	LS U	IKLA	CII WI	11151K1	ES IIIC.						
OCCUPIED: YES NO	XX											
BUILDING ELEMENT	1	thru 5 (	CONDIT	ION		NOTES & COMMENTS						
	VERY POOR				VERY GOOD							
Foundation Type:	POOR				GOOD	SOLID OR SLAB FOUNDATION IN						
Piers						FAIR SHAPE						
Solid			3									
Slab												
Front Porch Type:						SAME AS SLAB AND FOUNDATION						
Wood			3									
Concrete												
Exterior Doors and Windows						ALL DOOR TYPES IN POOR SHAPE,						
Type:						NEED REPLACED						
Wood		2										
Vinyl												
Aluminum												
Roof Underlay Type:						OSB OR PLYWOOD UNDERLAY IN						
OSB/ Plywood		2				POOR SHAPE FROM WATER						
1x6						DAMAGE . NEEDS REPLACED						
metal												
Roof Surface Type: Metal						PART SHINGLES AND PART						
3-Tab Shingles		2				METAL, NEEDS REPLACED						
Dimensional Shingles						,						
Chimney						N/A						
Siding Type:						ALUMINUM AND WOOD LAP OR						
Wood Lap						MASONITE , ALL IN BAD SHAPE						
Vinyl			3			EXCEPT THE ALUMINUM						
Masonite			3									
Aluminum												
Fascia and Trim Type						WOOD TRIM NEEDS REPLACED, IT						
Wood		2				IS ALREADY MISSING IN MOST						
Vinyl Coil						AREAS						
Interior Doors Type:			3			ALL WOOD OR HOLLOW DOORS						
Hollow Wood						NEED REPAIRED OR REPLACED						
Solid Wood					1							

Interior Walls Type Wood Frame Metal Frame					3			WAT	OD FRAMED WALLS HAVE TER DAMAGE AND NEED AIRED			
Sheetrock								KEF	AIRED			
Stucco												
Ceilings Type:								CHE	ETROCK CEILINGS NEED			
Sheetrock									LACED FROM WATER			
Stucco				2					IAGE			
Ceiling Tile								DAN	IAGE			
Flooring Underlay Type:								SIA	B , CONCRETE			
1x6 center match					3			SLA	B, CONCILIE			
OSB												
Plywood												
Flooring Surfaces Type:								MIX	ED FLOOR COVERINGS MOST			
Carpet									DAMAGED FROM WATER			
Linoleum				2					NEED REPLACED			
Hard Wood												
Vinyl												
Electrical								NOT	TO CODE			
Heating									TO CODE			
Plumbing								NOT	TO CODE			
In my opinion, this structure		is	X	is not	Suitable for human habitation.							
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.							
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.							
In my opinion, this structure	X	is		is not	A pı	A public safety hazard and should be condemned immediately.						
		~=										
							ANTED:					
PROPERTY WAS NOTS	SECU	J <b>K</b> E	U AT	TIME	OF IN	SPECT	ION ANL	IS A	HAZARD TO THE PUBLIC			
Tim Renshaw, Chief Building							Other Signature					
Tim Lens												
Municinal Building 300 South Church Joneshoro Ar / Phone 870-336-7194/ Fay 870-336-1358												
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358												