

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4-24-1	5		1								
PROPERTY ADDRESS:	1110 Belt											
PROPERTY OWNER:	Judy Shelton											
OCCUPIED: YES NO	XX											
BUILDING ELEMENT		1	thru 5 (CONDIT	ION	NOTES & COMMENTS						
	1	VERY				VERY						
Foundation Type:		POOR				GOOD	Completely rotted out					
Piers		5	g apparatus de de la constante				Completely follow out					
Solid	-											
Slab												
Front Porch Type:	-						Concrete in good shape					
Wood					2							
Concrete												
Exterior Doors and Windows					2		Decent shape					
Type:					2							
Wood												
Vinyl	-											
Aluminum												
Roof Underlay Type:					2		Looks good					
OSB/ Plwood					-	union representation of the control						
1x6												
metal Notes					-		Decent shape					
Roof Surface Type: Metal			-		2		Decent shape					
3-Tab Shingles	Sage vacantina di si											
Dimensional Shingles												
Chimney Siding Type:					2		Outside of house looks decent but upon					
Siding Type: Wood Lap			garante and an analysis of the second				entering ,floor is gone completely					
Vinyl												
Masonite												
Aluminum												
Fascia and Trim Type							Outside of house looks decent but upon					
Wood					2		entering ,floor is gone completely					
Vinyl Coil			- Consequence									
Interior Doors Type:							Outside of house looks decent but upon					
Hollow Wood				3			entering ,floor is gone completely					
Solid Wood												

Interior Walls Type					3	Outside of house looks decent but upon			
Wood Frame	wateres.		and the same of th	genous-	Will be seen and the seen and t	entering, floor is gone completely			
Metal Frame	and the same of th		All States	- Constitution of the Cons					
Sheetrock	MARKATAN.	-	sacra-	-					
Stucco									
Ceilings Type:	-	-	and the same of th	-	3	Outside of house looks decent but upon			
Sheetrock	-	-	-	TOTAL STATE OF THE		entering ,floor is gone completely			
Stucco	1	- Name of the last	1	-					
Ceiling Tile									
Flooring Underlay Type:	1	1	5	- The second		Outside of house looks decent but upon			
1x6 center match	1		,	-	and the second	entering ,floor is gone completely			
OSB	1		9	- Consequence of the Consequence	8				
Plywood	-								
Flooring Surfaces Type:	1	1	5	Name of the last o		Outside of house looks decent but upon			
Carpet	, ,	-	-	-		entering ,floor is gone completely			
Linoleum	7	-		-	And the state of t				
Hard Wood	,	**	,	-	100000000000000000000000000000000000000				
Vinyl									
Electrical			1	4		Not to code			
Heating				4		Not to code			
Plumbing				4		Not to code			
			,						
			T = -						
In my opinion, this structure	1	is	X	is not	Suitable	Suitable for human habitation.			
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	X	is not	Economi	ically feasible for rehabilitation.			
In my opinion, this structure	X	is		is not	A public	A public safety hazard and should be condemned immediately.			
E	MED	CE	NOV	ACTIO	NI IC WAT	RRANTED: YES NO XX			
Est	/IEIX	GE	IC1	ACTIO	N 15 WAD	CRANIED: IES NO AA			
	Accommend								
Tim Renshaw, Chief Building Inspector						Other Signature			
2-1									
1 day									
Municipal Bu	ilding	, 300	Sout!	n Church	Jonesboro,	Ar./ Phone 870-336-7194/ Fax 870-336-1358			