

<u>AFFIDAVIT</u>
Jacqueline + Ronnie Stanbeck
919 W Matthews Ave.
Jonesboro, AX 72401
RE: 600 + 602 N Church St. Jonesboro, AR 724
01-144074-10300
I, Michael McQuay, a Code Enforcement Officer, being duly sworn upon oath, that I served the
attached notice(s) upon each of the persons or firms therein addressed, by depositing copies
thereof in the United States Mail, enclosed within envelopes plainly addressed, as shown with
postage fully prepaid, at the Jonesboro, Arkansas Post Office located at 310 East Street, Suite A., before 3:00 P.M., on the
Michael McQuay Jonesboro Code Enforcement
Subscribed and sworn to before me the 13th day of JUIM, 2022.
Notary Public TOSHA MOSS MY COMMISSION # 12397080 EXPIRES: January 17, 2024 Craighead County

My commission expires: \an. 17, 2024



Notice of Violation

Date: 07/13/2022

JACQUELINE & RONNIE STANBECK 919 W MATTHEWS AVE JONESBORO, AR 72401

SUBJECT: 600 & 602 N CHURCH ST JONESBORO, AR 72401 PARCEL # 01-144074-10300

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley Code Enforcement Officer

P.O. Box 1845 Jonesboro, AR 72403

CE20-8622

Sign if served in person

Code Enforcement Officer Signature, if delivered in person

Property Owner/Interested Party Signature, if delivered in person



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

BUILDING INSPECTION REPORT

DATE OF	7/13/2022			CAS	E NUMB	ER: CE20-8622
INSPECTION: PROPERTY ADDRESS:	COO NI CHILIP	CII D	I D OF	T U O	4.440= :	10200
PROPERTY ADDRESS:	600 N CHUR	CH P	ARCE	L # 01	-144074-	10300
PROPERTY OWNER:	JACQUELIN	E & R	ONNI	E STA	NBECK	
		NE PA	RCEL	. ENTI	RE PARC	CEL IS BEING CONDEMNED.
	OXX					
BUILDING ELEMENT	1 t	hru 5 C	ONDIT	ION		NOTES & COMMENTS
	VERY POOR				VERY GOOD	
Foundation Type:				4		SOLID SLAB FOUNDATION.
Piers						NO MAJOR DEFECTS OR
Solid						ISSUES
Slab						
Front Porch Type:						N/A
Wood						
Concrete						
Exterior Doors and Window	rs 1					ALL DOORS AND WINDOWS
Type:						ARE BROKEN, BOARDED, OR
Wood						BOTH. ALL DOORS AND
Vinyl Aluminum						WINDOWS NEED REPLACED.
		2				THE DOOR IS SUSSIBLE.
Roof Underlay Type: OSB/ Plywood		2				THE ROOF IS SAGGING.
1x6						UNDERLAY AND RAFTERS
metal						NEED REPAIRED AND/OR REPLACED.
Roof Surface Type: Metal	1					SHINGLES ARE DAMAGED
3-Tab Shingles	1					AND/OR MISSING, SHINGLES
Dimensional Shingles						NEED REPLACED.
Chimney						N/A
Siding Type:			3			THE VINYL SIDING HAS A
Wood Lap						FEW PLACES WITH DAMAGE
Vinyl						IN NEED OF REPAIR. THE
Masonite						BRICK IS IN GOOD SHAPE.
Aluminum						Didding in Good Similar.
Fascia and Trim Type	1					WOOD FASCIA AND TRIM IS
Wood						ROTTEN, FALLING OFF, AND
Vinyl Coil						SHOWS SIGNS OF WILDLIFE DAMAGE. NEEDS REPLACED.
Interior Doors Type:	1					ALL INTERIOR DOORS ARE
Hollow Wood						MISSING OR DAMAGED AND
Solid Wood						NEED REPLACED.
Interior Walls Type		2			110	SHEETROCK WALLS WITH
Wood Frame						DAMAGE FROM METAL THEIVES
Metal Frame						AND WILDLIFE. MUCH OF THE
Sheetrock						SHEETROCK NEEDS REPAIRED OR REPLACED

Ceilings Type: Sheetrock Stucco Ceiling Tile Flooring Underlay Type: 1x6 center match OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this structure	MOST THE CEILING IS MISSING OR IS DAMAGED. NEEDS REPLACED. N/A		
Stucco Ceiling Tile Flooring Underlay Type: 1x6 center match OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not	NEEDS REPLACED.		
Ceiling Tile Flooring Underlay Type: 1x6 center match OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Flooring Underlay Type: 1x6 center match OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure	N/A .		
1x6 center match OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure	N/A		
OSB Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Plywood Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Carpet Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure	CONTRACTOR AND		
Linoleum Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure	CONCRETE. N/A		
Hard Wood Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Vinyl Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure			
Electrical Heating Plumbing In my opinion, this structure In my opinion this is XX is not structure In my opinion this			
Heating Plumbing In my opinion, this structure In my opinion this is XX is not is XX	NOT TO CODE		
Plumbing 1 In my opinion, this structure is XX is not structure In my opinion this is XX is not is not is XX is XX is not is XX is XX is not is XX is	NOT TO CODE		
In my opinion, this structure is XX is not is XX is XX is not is XX is XX is not is XX	NOT TO CODE		
In my opinion this is XX is not	NOT TO CODE		
regionalists of the production of the control of th	t Suitable for human habitation.		
	Physically feasible for rehabilitation.		
In my opinion, this structure is XX is not	Economically feasible for rehabilitation.		
In my opinion, this structure XX is is not	A public safety hazard and should be condemned immediately.		
EMERGENCY ACTION	IS WARRANTED: YES NO XX		
PROPERTY WAS NOT SECURE AT TIME OF			
Tim Renshaw, Chief Building Inspector	David Cooley, Code Enforcement		
Tim Lensen	Toly-		
Municipal Building, 300 South Church Jor			



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

BUILDING INSPECTION REPORT

INSPECTION: PROPERTY ADDRESS: 602 N CHURCH PARCEL # 01-144074-10300 PROPERTY OWNER: JACQUELINE & RONNIE STANBECK PROPERTY HAS TWO BUILDINGS ON ONE PARCEL. ENTIRE PARCEL IS BEING CONDEMNED. OCCUPIED: YES NO XX BUILDING ELEMENT 1 thru 5 CONDITION NOTES & COMMENTS VERY POOR GOOD Foundation Type: 1 PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS Slab Slab REPAIRED Front Porch Type: N/A Wood Concrete Exterior Doors and Windows Type: ALL DOORS AND WINDOWS Type: ARE BROKEN, BOARDED, OR	DATE OF	7/13/2022		CASI	E NUMB	BER: CE20-8622
PROPERTY OWNER: JACQUELINE & RONNIE STANBECK PROPERTY HAS TWO BUILDINGS ON ONE PARCEL, ENTIRE PARCEL IS BEING CONDEMNED. OCCUPIED: YES NO XX BUILDING ELEMENT 1 thru 5 CONDITION NOTES & COMMENTS VERY POOR GOOD Foundation Type: 1 PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED Front Porch Type: N/A Wood Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS						
PROPERTY HAS TWO BUILDINGS ON ONE PARCEL. ENTIRE PARCEL IS BEING CONDEMNED. OCCUPIED: YES NO XX BUILDING ELEMENT 1 thru 5 CONDITION NOTES & COMMENTS VERY POOR GOOD Foundation Type: 1 PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS Slab Front Porch Type: N/A Wood Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS	PROPERTY ADDRESS:	602 N CHUR	CH PAR	CEL # 01-	144074-	10300
PROPERTY HAS TWO BUILDINGS ON ONE PARCEL. ENTIRE PARCEL IS BEING CONDEMNED. OCCUPIED: YES NO XX BUILDING ELEMENT 1 thru 5 CONDITION NOTES & COMMENTS VERY POOR GOOD Foundation Type: 1 PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS Slab Front Porch Type: N/A Wood Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS	PROPERTY OWNER:	JACQUELIN	E & RON	NIE STA	NBECK	
BUILDING ELEMENT 1 thru 5 CONDITION NOTES & COMMENTS VERY POOR Foundation Type: Piers Solid Slab Front Porch Type: Wood Concrete Exterior Doors and Windows 1 thru 5 CONDITION NOTES & COMMENTS VERY GOOD PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED N/A ALL DOORS AND WINDOWS	PROPERTY HAS TWO BU	ILDINGS ON C	ONE PARC	EL. ENTI	RE PARC	CEL IS BEING CONDEMNED.
Foundation Type: Piers Solid Slab Front Porch Type: Wood Concrete Exterior Doors and Windows PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED N/A ALL DOORS AND WINDOWS						DELICO CONDENIALIDA
Foundation Type: Piers Solid Slab Front Porch Type: Wood Concrete Exterior Doors and Windows PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED N/A ALL DOORS AND WINDOWS	BUILDING ELEMENT	1 t	hru 5 CON	DITION	11	NOTES & COMMENTS
Foundation Type: Piers Piers Poly DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED Front Porch Type: Wood Concrete Exterior Doors and Windows PIER FOUNDATION WITH DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED N/A ALL DOORS AND WINDOWS						
Piers Solid Solid Slab Front Porch Type: Wood Concrete Exterior Doors and Windows DAMAGE. CRACKS IN MASONRY. NEEDS REPAIRED N/A ALL DOORS AND WINDOWS	Foundation Type:	1 1			GOOD	PIER FOLINDATION WITH
Solid MASONRY. NEEDS Slab REPAIRED Front Porch Type: N/A Wood Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS						
Slab Front Porch Type: Wood Concrete Exterior Doors and Windows REPAIRED N/A N/A ALL DOORS AND WINDOWS						
Front Porch Type: Wood Concrete Exterior Doors and Windows N/A ALL DOORS AND WINDOWS						
Wood Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS						1475 COS SIBILO / TOPOS ASSESSED (MOS) (1500 MOS)
Concrete Exterior Doors and Windows 1 ALL DOORS AND WINDOWS						IVA
Exterior Doors and Windows 1 ALL DOORS AND WINDOWS	100 Care 100					
	Exterior Doors and Windov	vs 1				ALL DOORS AND WINDOWS
THE BROKEN, BOTHEDED, OR						
Wood BOTH. ALL DOORS AND						
Vinyl WINDOWS NEED REPLACED.						Principle of the property of the control of the con
Aluminum						WANDS WE REED TENEDED.
Roof Underlay Type: 2 THE ROOF IS SAGGING.	Roof Underlay Type:		2			THE ROOF IS SAGGING.
OSB/ Plywood UNDERLAY AND RAFTERS						
1x6 NEED REPAIRED AND/OR	1x6					
metal REPLACED.	metal					The state of the s
Roof Surface Type: Metal SHINGLES ARE DAMAGED	Roof Surface Type: Metal	1				
3-Tab Shingles AND/OR MISSING. SHINGLES						AND/OR MISSING. SHINGLES
Dimensional Shingles NEED REPLACED.						
Chimney N/A	Chimney					N/A
Siding Type: 4 BRICK EXTERIOR.	Siding Type:				4	BRICK EXTERIOR.
Wood Lap						
Vinyl						
Masonite	Masonite					
Aluminum	Aluminum					
Fascia and Trim Type 1 WOOD FASCIA AND TRIM IS	Fascia and Trim Type	1				
Wood ROTTEN, FALLING OFF, AND	Wood					
Vinyl Coil SHOWS SIGNS OF WILDLIFE DAMAGE. NEEDS REPLACED.	Vinyl Coil					
Interior Doors Type: ALL INTERIOR DOORS ARE	Interior Doors Type:	1				
Hollow Wood MISSING OR DAMAGED AND						
Solid Wood NEED REPLACED.		-				
Interior Walls Type 2 SHEETROCK WALLS WITH	Control of the Contro		2			
Wood Frame DAMAGE FROM METAL THEIVES						
Metal Frame AND WILDLIFE, MUCH OF THE						그 그 그는 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
Sheetrock Sheetrock Sheetrock Sheetrock Sheetrock						

Stucco							
Ceilings Type: Sheetrock Stucco Ceiling Tile			1		MOST THE CEILING IS MISSING OR IS DAMAGED. NEEDS REPLACED.		
Flooring Underlay Type: 1x6 center match OSB Plywood		1		FLOOR IS SAGGING, SOFT, AND FALLING IN. UNDERLAY AND JOISTS NEED REPAIRED AND/OR REPLACED			
Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl				2	MOST OF THE FLOOR SURFACES HAVE DAMAGE AND NEEDS REPLACED.		
Electrical			1		NOT TO CODE		
Heating			1		NOT TO CODE		
lumbing 1		1		NOT TO CODE			
In my opinion, this structure		is	XX	is not	Suitable for human habitation.		
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.		
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.		
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.		
		Company of the Company	A STATE OF THE STA		S WARRANTED: YES NO XX		
PROPERTY WAS NOT S	ECUR	EA	T TIM	E OF IN	ISPECTION.		
Tim Renshaw, Chief Buildin	ng Insp	ector			David Cooley, Code Enforcement		
Jain Lens					200		
Municipal Build	ling, 30	0 Sou	ith Chu	rch Jone	sboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358		