

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	9-22-16										
PROPERTY ADDRESS:	119 COLEMAN										
PROPERTY OWNER:	STEVE OR MARY PENEBAKER										
OCCUPIED: YES NO X											
BUILDING ELEMENT	1 thru 5 CON	DITION	NOTES & COMMENTS								
	VERY POOR	VERY GOOD									
Foundation Type: Piers Solid Slab	2		PIERS ,NEEDS REPAIRED OR REPLACED								
Front Porch Type: Wood Concrete	2		ROTTED WITH HOLES IN FLOOR								
Exterior Doors and Windows Type: Wood Vinyl	2		MIXED TYPES , ALL ARE IN PLACE , SHOULD BE REPLACED								
Aluminum Roof Underlay Type: OSB/ Plywood 1x6 metal	2		NEEDS REPLACED,								
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles	2		NEEDS REPLACED WITH DECKING								
Chimney Siding Type: Wood Lap Vinyl Masonite Aluminum	2		N/A ALL WOOD AND MASONITE NEEDS REPLACED OR REPAIRED IF POSSIBLE								
Fascia and Trim Type Wood Vinyl Coil	2		ALL WOOD , ROTTED AND WEATHERED , NEEDS TO BE REPLACED								
Interior Doors Type: Hollow Wood Solid Wood		3	HOUSE WAS SECURED , DID NOT GO INSIDE								

Interior Walls Type Wood Frame									SE WAS SECURED , DID NOT NSIDE		
Metal Frame								00 1	SIDE		
Sheetrock											
Stucco											
Ceilings Type:								HOU	SE WAS SECURED , DID NOT		
Sheetrock									NSIDE		
Stucco											
Ceiling Tile											
Flooring Underlay Type:								HOU	SE WAS SECURED , DID NOT		
1x6 center match								GO II	NSIDE		
OSB											
Plywood											
Flooring Surfaces Type:								HOU	SE WAS SECURED , DID NOT		
Carpet								GO II	NSIDE		
Linoleum											
Hard Wood											
Vinyl											
Electrical					3			NOT	TO CODE		
Heating					3			NOT	TO CODE		
Plumbing					3	3 NOT TO CODE			TO CODE		
					-						
In my opinion, this structure		is	Χ	is not	Suitable for human habitation.						
In my opinion this structure	Χ	is		is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	Χ	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	Χ	is		is not	A public safety hazard and should be condemned immediately.						
F	EME	RGE	ENCY	Y ACTI	ON IS	WARR	RANTED	: YES	X NO		
Tim Renshaw, Chief Building							Other Signature				
Thing theread											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											