

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	1-23-17										
PROPERTY ADDRESS:	420 GORDON HARVEY R WILLIAMS										
PROPERTY OWNER:											
					,						
OCCUPIED: YES NO	XX										
	ı										
BUILDING ELEMENT	1	thru 5 CO	ONDITION		NOTES & COMMENTS						
	VERY POOR			VERY GOOD							
Foundation Type:					FALLING OFF PIERS ,SHIFTING						
Piers		_			,						
Solid		2									
Slab											
Front Porch Type:					ROTTED AND NEEDS REPLACED						
Wood	1										
Concrete											
Exterior Doors and Windows					MISSING AND BOARDED UP						
Type:	1										
Wood											
Vinyl											
Aluminum											
Roof Underlay Type:					NEEDS REPLACED ,UNLEVEL AND						
OSB/ Plywood		2			SAGGING						
1x6											
metal											
Roof Surface Type: Metal					OLD AND NEEDS REPLACED OR						
3-Tab Shingles		2			REPAIRED						
Dimensional Shingles											
Chimney					N/A						
Siding Type:					NEEDS REPLACED OR REPAIRED						
Wood Lap		2			FROM WATER DAMAGE BECAUSE						
Vinyl					OF NO PAINT						
Masonite											
Aluminum											
Fascia and Trim Type					ROTTED IN AREAS ,SAME AS						
Wood		2			SIDING						
Vinyl Coil											
Interior Doors Type:					REMOVED OR OFF HINDGES, WILL						
Hollow Wood		2			NOT CLOSE BECAUSE OFF						
Solid Wood					STRUCTURE FAILURE						

Interior Walls Type									DD FRAMING ,SEEMS TO BE		
Wood Frame			I		3				ACT ,SOME NEED REPAIRED		
Metal Frame			I					BECA	ASE OF SAGGING FLOORS		
Sheetrock			I								
Stucco					l <u></u>		l				
Ceilings Type:								SOM	E AREAS NEED REPLACED,		
Sheetrock			I	2				WAT	ER DAMAGED		
Stucco			I								
Ceiling Tile					l		l	<u> </u>			
Flooring Underlay Type:								ROT	TED AND WEAK ,WATER		
1x6 center match			I	2				DAM	IAGED,NEEDS REPLACED		
OSB			I								
Plywood			I								
Flooring Surfaces Type:								ALL	NEEDS TO BE REPLACED DUE		
Carpet			I					TO W	VATER DAMAGE		
Linoleum			I	2							
Hard Wood			I								
Vinyl			ļ								
Electrical				2				NOT	TO CODE		
Heating				2				NOT	TO CODE		
Plumbing				2				NOT	TO CODE		
In my opinion, this structure		is	X	is not	Suitable for human habitation.						
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A pı	A public safety hazard and should be condemned immediately.					
							ANTED:				
H	IOUS	SE W	VAS J	NOT SE	<u> CURE</u>	ED AT T	TIME OF	INSPE	CTION		
Tim Renshaw, Chief Building	Inspe	ctor		 					Other Signature		
Tim Reisnaw, Ciner Building Inspector Other Signature											
Immy Henrol											
M 11 1D DV 200 G 11 GV 1 X 1 X 1 X 200 CC 740 4/7 070 CC 740 77											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											