

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	3-6-17											
PROPERTY ADDRESS:	615 E. WORD											
PROPERTY OWNER:	CANDIS P. & LAMAR CHARLES MABRY											
OCCUPIED: YES NO	X											
BUILDING ELEMENT	1	1 thru 5 CONDITION				NOTES & COMMENTS						
BOILDING EDENTERY	VERY	I	1011	VERY	TOTES & COMMENTS							
	POOR				GOOD							
Foundation Type:						PIERS , SOFT FLOORS WATER						
Piers			3			DAMAGED						
Solid												
Slab												
Front Porch Type:						PORCH ON PIERS IN FAIR SHAPE						
Wood			2									
Concrete			3									
Exterior Doors and Windows						SOME DOORS MISSING , SOME						
Type:			3			WITH NO HARDWARE, NEED						
Wood						REPLACED						
Vinyl												
Aluminum												
Roof Underlay Type:						NEEDS REPAIRED IN SEVERAL						
OSB/ Plywood		2				AREAS						
1x6		2										
metal												
Roof Surface Type: Metal						SHINGLES NEED REPLACED						
3-Tab Shingles		2										
Dimensional Shingles												
Chimney						N/A						
Siding Type:						WOOD SIDING IN TACT, IN FAIR						
Wood Lap			2			SHAPE						
Vinyl			3									
Masonite												
Aluminum												
Fascia and Trim Type						SAME AS SIDING						
Wood			3									
Vinyl Coil												
Interior Doors Type:						ALL NEED WORK OR						
Hollow Wood		2				REPAIRED/REPLACED						
Solid Wood												

Interior Wells Type								CHE	ETROCK WALLS IN FAIR		
Interior Walls Type Wood Frame									PE, NEED SOME REPAIR		
Metal Frame								зпа	re, need some keraik		
						4					
Sheetrock											
Stucco								0014	E DOCK GOLEE AND EN		
Ceilings Type:									E ROCK SOME 2X4 TILES,		
Sheetrock									TER DAMAGED THROUGHOUT,		
Stucco				2				NEE	DSREPLACED / REPAIRED		
Ceiling Tile											
Flooring Underlay Type:									Γ APOTS FROM WATER		
1x6 center match				2				DAM	IAGED, NEEDS REPAIRED		
OSB				2							
Plywood											
Flooring Surfaces Type:									CARPET AND LINOLEUM,		
Carpet			1					NEE	DS REPLACED		
Linoleum			1								
Hard Wood											
Vinyl											
Electrical				2				NOT	TO CODE		
Heating				2				NOT	TO CODE		
Plumbing				2				NOT	TO CODE		
In my opinion, this structure		is	X	is not	Suitable for human habitation.						
In my opinion this structure	X	is		is not	Physically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	Economically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	A public safety hazard and should be condemned immediately.						
	1	ı	1		1				, , , , , , , , , , , , , , , , , , ,		
							RANTED				
Н	OUS	E W	AS 1	VOT SE	CURE	D AT I	TIME OF	INSPE	CTION		
Tim Renshaw, Chief Building	Inspe	ctor							Other Signature		
Times Levis											
									-		
Municipal Building 300 South Church Jonesboro, Ar / Phone 870-336-7194/ Fax 870-336-1358											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											