

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	6-19-17					
PROPERTY ADDRESS:	1901 NATIO	)NAL I	RD.			
PROPERTY OWNER:	CAMBRIDO	GE CA	PITAL	INVES	STMENT	rs -
OCCUPIED: YES NO	X					
BUILDING ELEMENT	1	thru 5 (	CONDIT	ION		NOTES & COMMENTS
	VERY				VERY	
Foundation Type:	POOR				GOOD	SLAB FOUNDATION IN FAIR
Piers						SHAPE
Solid			3			Sinte
Slab						
Front Porch Type:						CONCRETE PORCH IN GOOD
Wood			3			SHAPE
Concrete						
Exterior Doors and Windows						SOME MISSING , ALL NEED
Type:						REPLACED, SOME BOARDED UP
Wood		2				,
Vinyl		2				
Aluminum						
Roof Underlay Type:						1X6 UNDERLAY IN FAIR SHAPE
OSB/ Plywood			2			
1x6			3			
metal						
Roof Surface Type: Metal						SHINGLES NEED REPLACED
3-Tab Shingles			3			
Dimensional Shingles						
Chimney						
Siding Type:						VINYL NEEDS REPLACED, FIRE
Wood Lap			3			DAMAGED
Vinyl						
Masonite						
Aluminum						GANES AG OFFINIO
Fascia and Trim Type			3			SAME AS SIDING
Wood			3			
Vinyl Coil		-		-		ALL MEED TO BE BEDLACED BYTE
Interior Doors Type:		2				ALL NEED TO BE REPLACED DUE
Hollow Wood						TO FIRE DAMAGE
Solid Wood					]	

Interior Walls Type				2			ALL HAVE FIRE DAMAGE AND		
Wood Frame				2			NEED RPLACED		
Metal Frame									
Sheetrock									
Stucco									
Ceilings Type:				_			ALL HAVE FIRE AND WATER		
Sheetrock				2			DAMAGE AND NEED REPLPACED		
Stucco							OR REPAIRED		
Ceiling Tile									
Flooring Underlay Type:							SOME AREAS HAVE HEAVY		
1x6 center match							DAMAGE AND NEED EPLACED		
OSB					3				
Plywood									
Flooring Surfaces Type:							ALL HAVE DAMAGE FROM FIRE		
Carpet							AND WATER ,NEEDS REPLACED		
Linoleum				2			·		
Hard Wood									
Vinyl									
Electrical				2			NEEDS REPAIR OR REPLACED		
Heating				2			NEEDS REPLACED		
Plumbing					3		NEEDS REPAIR		
		t							
In my opinion, this structure		is	X	is not	Suitable for human habitation.				
In my opinion this structure	X	is		is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.				
					_				
E							D: YES X NO		
	I	HOM	IE NI	EEDS TO	O BE S	SECURED OR	RAZED		
Tim Renshaw, Chief Building Inspector							Other Signature		
Tim Len 82									
Municipal Bu	ilding	, 300	South	Church	Jonesb	oro, Ar./ Phone 87	70-336-7194/ Fax 870-336-1358		