

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	3-7-16					
PROPERTY ADDRESS:	732 FRONT S					
PROPERTY OWNER:	DON BRIDG	ER				
						,
OCCUPIED: YES NO	ΧX					
BUILDING ELEMENT	1 1	hru 5 CC	ONDITI	ON		NOTES & COMMENTS
BUILDING ELEMENT		1 thru 5 CONDITION  VERY			VERY	TOTES & COMMENTS
	POOR				GOOD	
Foundation Type:						ON CONCRETE SLAB, CRACKED
Piers						AND UNEVEN THROUGHOUT
Solid						
Slab		2				
Front Porch Type:						SLAB PORCH , SAME AS
Wood						FOUNDATION
Concrete		2				
Exterior Doors and Windows						WOODEN FRONT DOOR,
Type:						BOARDED UP AND NO
Wood		2				WINDOWS,TWO ROLL UP DOORS
Vinyl						ALSO BOARDED UP AN NO
Aluminum						WINDOWS
Roof Underlay Type:						ENTIRE ROOF AND CEILING JOIST
OSB/ Plywood	1					HAVE FALLEN INTO THE
1x6						BUILDING
metal						
Roof Surface Type: Metal						N/A
3-Tab Shingles	1					
Dimensional Shingles						
Chimney						N/A
Siding Type:						MASONITE LAP SIDING, ROTTED
Wood Lap						AND WEATHERED NEEDS
Vinyl						REPLACED
Masonite		2				
Aluminum						
Fascia and Trim Type						MOST OF IT GONE WITH THE
Wood	1					ROOF,NEEDS REPLACED
Vinyl Coil						
Interior Doors Type:						N/A
Hollow Wood						
Solid Wood						

Interior Walls Type Wood Frame				2	WOOD FRAM ARE WEATHERED AND ROTTED FROM RAIN AND				
Metal Frame					NO ROOF AND SIDING MISSING				
Sheetrock					THE ROOF THE SIDING MISSING				
Stucco									
Ceilings Type:					CEILING HAS FALLEN INTO				
Sheetrock			1		BUILDING				
Stucco									
Ceiling Tile									
Flooring Underlay Type:					CONCRETE SLAB EXPOSED				
1x6 center match									
OSB				2					
Plywood									
Flooring Surfaces Type:					N/A				
Carpet									
Linoleum									
Hard Wood									
Vinyl									
Electrical			1		NOT TO CODE				
Heating			1		NOT TO CODE				
Plumbing			1		NOT TO CODE				
In my opinion, this structure		is	XX	is not	Suitable for human habitation.				
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.				
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.				
	<u> </u>			1					
E	MER	GE	NCY A	ACTION	IS WARRANTED: YES X NO				
				<u> </u>					
Tim Renshaw, Chief Building Inspector			+		Other Signature				
Tim Ferrs									
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358									