

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

BUILDING INSPECTION REPORT

DATE OF INSPECTION:	SEPTEMBER 26, 2022	CASE NUMBER: CE20-8226
PROPERTY ADDRESS:	305 AIRPORT RD.	
PROPERTY OWNER:	I & C Rentals Inc.	

BUILDING IS METAL COMMERCAL ON A SLAB FOUNDATION. THE PROPERTY BURNED ON FEBURARY 18, 2022. NO REPAIR WORK HAS STARTED. NO PERMITS PULLED. THE FRONT OF THE BUILDING WAS EXTENSIVLY DAMAGED BY THE FIRE. THE ROOF I-BEAMS ARE BOWED AND SAGGING FROM THE FIRE DAMAGE. THEY MUST BE MORE CLOSLEY INSPECTED TO VERIFY THEIR STRUCTUAL INTEGRIDY. THE METAL SIDING WHICH IS UNDER VINYL SIDING IS COMPRAMISED. MUCH OF THE VINYL SIDING ON THE EAST AND SOUTHEAST SIDES IS MELTED. ALL SIDING NEEDS REPLACED. ALL WINDOWS AND DOORS ARE EITHER BROKEN OR BOARDED. THE INTIEOR DROP CEILING HAS FALLEN IN MUCH OF THE BUILDING. AREAS THAT HAVE NOT FALLEN SHOW SMOKE AND WATER DAMAGE. ELECTRICAL IS NOT IN CODE, WAS DAMAGED GREATLY IN THE FIRE, AND WOULD HAVE TO BE COMPLETELY REPLACED. THERE IS WIRING, CONDUET, PIPING, CEILING SUPPORTS, LIGHTING FIXTURES, AND MUCH MORE FALLING FROM THE CEILING. THE BUILDING IS A HAZARD TO THE HEALTH, WELFARE, AND SAFETY OF THE PUBLIC. THE BUILDING SHOULD BE RAZED IMMEDIATELY TO ENSURE THE SAFETY OF LOCAL CHILDREN AND OTHER CITIZENS. NOT TO MENTION THE BLIGHT TO THE COMMUNITY. PROPERTY WAS NOT SECURED AT THE TIME OF INSPECTION.

In my opinion, this structure		Is	XX	Is not	Suitable for human habitation.
In my opinion, this structure		Is	XX	Is not	Physically feasible for rehabilitation.
In my opinion, this structure		Is	XX	Is not	Economically feasible for rehabilitation.
In my opinion, this structure	XX	Is		Is not	A public safety hazard and should be condemned immediately.

EMERGENCY ACTION IS WARRANTED: YES NO XX

Tim Renshaw, Chief Building Inspector	David Cooley, Code Enforcement
Tim Ferrolm	Toly

Municipal Building, 300 South Church Jonesboro, AR/ Phone 870-336-7194/Fax 870-336-1358