

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	TE OF INSPECTION: 10-30-08						
PROPERTY ADDRESS: 1700 Howry							
PROPERTY OWNER:	Re	2009	Tollis	0~			
OCCUPIED: YES	NO.	12					
BUILDING ELEMENT			CONDITION				NOTES & COMMENTS
		VERY POOR				VERY GOOD	-
Foundation	-	1	2	3	4	5	Piers
Front Porch		1	2	3	4	5	Botter
Exterior Doors and Windows		1	(2)	3	4	5	Rotten
Roof Underlay		1	2	3	4	5	Rotter weather'd
Roof Surface		1	2	3	4	5	negther b
Chimney		1-		3	_4	5_	11/19
Siding		1	2	3	4	5	Aleminum
Facia and Trim		1	(2)	3	4	5	ROTTE WEATHER'S
Interior Doors		①	2	3	4	5	name ESIXT
Interior Walls			2	3	4	5	Rotter
Ceilings		0	2	3	4	5	FAlling OUT
Flooring Underlay		(1)	2	3	4	5	Botter
Flooring Surfaces			2	3	4	5	rone
Electrical		(1)	2	3	4	57	NOT UP TO CODE
Heating		1	2	3	4	5	Fire HAZAN
Plumbing		1	2	3	4	5	-
In my opinion, this structure		is 🔀	is not	suitab	le for l	numan h	abitation.
In my opinion this structure		is 🔀	is not	physically feasible for rehabilitation.			
In my opinion, this structure		is 🏻	is not	economically feasible for rehabilitation.			
In my opinion, this structure	X	is	is not	a public safety hazard and should be condemned.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO							
In my opinion, this structure		is	is not				d and should be condemned immediately.
Ten & Av		,		1		·	
Terry Adams, Certified Building Inspector			Craig Davenport, Fire Marshal				al Other Signature