



# City of Jonesboro

300 S. Church Street  
Jonesboro, AR 72401

## Signature Copy

Ordinance: O-EN-002-2022

---

**File Number: ORD-22:001**

**Enactment Number: O-EN-002-2022**

AN ORDINANCE DECLARING AN EXCEPTIONAL SITUATION AND WAIVING THE REQUIREMENTS OF COMPETITIVE BIDDING FOR FIRE TRUCK BODY WORK ON A DAMAGED FIRE DEPARTMENT TRUCK.

WHEREAS, the 2021 Pierce Pumper Truck was damaged at a fire on June 18, 2021, and,

WHEREAS, the City's insurance company's appraiser handled the transactions to their rules and regulations and.

WHEREAS, the G & W Diesel Service Inc of Memphis TN, the authorized dealer of the fire truck brand, and the city's insurance company agreed upon the work to be done for the price of \$43,970.32 which has been paid to the City on December 27, 2021 less \$1,000 deductible.

NOW THEREFORE, BE IT ORDAINED BY THE CITY COUNCIL OF THE CITY OF JONESBORO THAT:

Section 1: An exceptional situation exists requiring the waiving of the conditions of competitive bidding, so that competitive bidding requirements are hereby waived, and the insurance and body shop agreed on the price of repairs.

Section 2: Said expense will be paid from the insurance recovery monies, paid by Arkansas Municipal League Vehicle Program, and the Fire Department vehicle repair line for the deductible.

PASSED AND APPROVED THIS 18TH DAY OF JANUARY 2022.

Date: 12/15/2021 06:27 PM  
 Estimate ID: EA-03790  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* Jonesboro Area

## Arkansas Municipal League

Vehicle Program P.O. Box 38, North Little Rock, AR 72115

Damage Assessed By: Keith Selby

Supplements To: Keith Selby (keith@eclipseappraisal.com) or Call  
 (870) 273-6497

Classification: Field

Type of Loss: Comprehensive  
 Date of Loss: 6/18/2021  
 Payer: Insurance  
 File Number: EA-03790  
 Claim Number: ~~24-00677-001~~

Deductible: 1,000.00

Insured: City of Jonesboro  
 Owner: ~~City of Jonesboro~~  
 Address: PO Box 1845, Jonesboro, AR 72403  
 Telephone: Home Phone: (870) 932-0740

Mitchell Service: 911000

Description: 21 Pierce Enforcer  
 VIN: 4P1BAAFF1MA022488  
 Mileage: 1  
 OEM/ALT: A  
 Parts Profile: Jonesboro Area

Parts Profile Version: 2

.line tem	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	REMOVE/REPLACE	Windshield	New	308.34 *	5.0*
2	900500	BDY *	REMOVE/REPLACE	Windshield Rubber Seal	New	113.36 *	0.0*
3	900500	BDY *	REMOVE/REPLACE	High Beam Headlamps	New	1,479.66 *	2.0*
4	900500	BDY *	REMOVE/REPLACE	Low Beam Headlamps	New	1,213.68 *	2.0*
5	900500	BDY *	REMOVE/REPLACE	Whelen M6 Front Mtd Red/Clear Lamps	New	723.97 *	2.0*
6	900500	BDY *	REMOVE/REPLACE	Front Mtd Led Amber Turn/Marker Lamps	New	383.76 *	2.0*
7	900500	BDY *	REMOVE/REPLACE	Lower Grille BTM STA Radiator Guard	New	293.02 *	1.0*
8	900500	BDY *	REMOVE/REPLACE	Whelen Freedom Light Bar End Cover (clear)	New	188.89 *	1.0*
9	900500	BDY *	REMOVE/REPLACE	Rt Front Center Hub Ccap, TAK 4 with gasket	New	71.24 *	0.5*
10	900500	BDY *	REMOVE/REPLACE	Right Whelen Lamp, Rt Bumper End M4 Series	New	297.44 *	0.5*
11	900500	BDY *	REMOVE/REPLACE	Led Amber Marker Lamps 4@11.99	New	47.97 *	1.0*
12	900500	BDY *	REMOVE/REPLACE	Rt Door Mirror Assembly	New	1,130.74 *	1.5*
13	900500	BDY *	ADD'L LABOR OP	Rt Side Graphics, striping, sinage, badging etc removal	Existing		12.0*
14							
15	900500	BDY *	ADD'L LABOR OP	Sut cleanup ....watersand and buff rt bodyside	Existing		16.0*
16	900500	BDY *	REMOVE/REPLACE	Reflective amber red truck light 4@16.64	New	66.56 *	0.3*
17	900500	BDY *	REMOVE/REPLACE	Right Upper, Center Cab Light Assy	New	206.57 *	0.5*
18	900500	BDY *	REMOVE/REPLACE	Rear MAO Led Marker Light	New	114.92 *	0.2*
19	900500	BDY *	REMOVE/REPLACE	Rt Side Whelen Scene/Flood Light	New	1,741.09 *	1.5*
20	900500	BDY *	REMOVE/REPLACE	Whelen M4 Chrome Bezels 4@33.18	New	132.73 *	0.0*
21	900500	BDY *	REMOVE/REPLACE	Complete Netting and Crosslay	New	2,346.24 *	2.0*
22	900500	BDY *	REMOVE/REPLACE	Roataor B6MM Series Light Lens	New	340.99 *	0.5*
23	900500	BDY *	REMOVE/REPLACE	Water Level Flashers..Red, Blue, Amber, Green	New	1,266.46 *	2.0*

ESTIMATE RECALL NUMBER: 12/15/2021 16:35:54 EA-03790

Mitchell Data Version: OEM: DEC\_21\_V

Alternate Parts: 12/15/2021 16:27:16

Copyright (C) 1994 - 2021 Mitchell International  
 All Rights Reserved

Software Version: 7.1.242

Page 1 of 4

24	900500	BDY *	REMOVE/REPLACE	TAG-Scene Lights (PRICE AND LABOR INCLUDES B New		
25				TAG-Flood Lights		
26				TAG-O NO 2 Speedlay C		
27				TAG-O NO 1 Speedlay C		
28				TAG-O NO 1 RT SIDE AUX INLET C		
29				TAG-O 2 "1/2" X LAY C		
30				TAG-O NO 1 CROSSLAY		
31				TAG-O NO 1 RT SIDE AUX INLET C		
32				TAG-O OPEN/CLOSED		
33				LABEL, CAB LIFT CONTROLS ST		
34				BEZEL, VERBAGE 1/2 W/DIKE, BLACK FACE, CHROME		
35				BEZEL, VERBAGE 1X2 W/DIKE ORANGE		
36				BEZEL VERBAGE 1X2 W/DIKE YELLOW		
37				BEZEL VERBAGE 1X2 W/DIKE GREEN		
38				BEZEL VERBAGE 1X2 W/DIKE WHITE		
39				BEZEL VERBAGE 1X2 W/DIKE BROWN		
40				BEZEL VERBAGE 1X2 W/DIKE BEIGE		
41				BEZEL VERBAGE 1X2 W/DIKE RUST		
42				BEZEL VERBAGE 1X2 W/DIKE LIGHT PURPLE		
43				BEZEL VERBAGE 1X2 W/DIKE BRIGHT ORANGE		
44	900500	BDY *	REMOVE/REPLACE	SAFETY LABEL....VEHICLE EGRESS, WARNING ALL New	22.88 *	0.5*
45	900500	BDY *	REMOVE/REPLACE	SAFETY LABEL....SECURE HOSE WARNING ENTANG New	36.14 *	0.5*
46	900500	BDY *	REMOVE/REPLACE	SAFETY LABEL....CAR RELIEF WARNING, PRESSURE New	21.06 *	0.5*
47	900500	BDY *	REMOVE/REPLACE	LABEL....CAB LIFT CONTROLS New	70.59 *	0.5*
48	900500	BDY *	REMOVE/REPLACE	LIGHT, RI-TAR SUPER LED WHITE ABS/CHROME New	156.65 *	1.0*
49	900500	BDY *	REMOVE/REPLACE	SWITCH ASSY W/HARNESS MOM BLACK/GREEN LIG New	466.83 *	2.0*
50	900500	BDY *	REMOVE/REPLACE	SWITCH GUARD, TGL 2 POS, RED SCI KEYWAY ON H New	62.79 *	1.0*
51	900500	BDY *	REMOVE/REPLACE	BOOT, TOGGLE SWITH, HALF BLACK, RUBBER (4) New	57.46 *	0.0*
52	900500	REF *	REFINISH/REPAIR	Sand and Refinish Rt Front cab corner & rt cabside Existing		24.0*
53				OEM Sikkens, Basecoat, Pierce 90, Clearcoat, wet		
54				Includes to wetsand and buff refinished area		
55	900500	BDY *	REMOVE/REPLACE	"Jonesboro Fire/Rescue" 23 karat (Yellow) New	1,878.11 *	2.0*
56	900500	BDY *	REMOVE/REPLACE	Gold Leaf "Shield" Passenger Crew Door New	2,336.36 *	2.0*
57	900500	BDY *	REMOVE/REPLACE	ISO CLASS 1, W/RUBY RED, SCL/L FOR CREW DOOR New	983.10 *	1.0*
58	900500	BDY *	REMOVE/REPLACE	GOLD LEAF STRIPE W/BLACK OUTLINE, RT CABSIDNew	1,207.40 *	6.0*
59	900500	BDY *	REMOVE/REPLACE	DIAMOND GRADE 6" REFLECTIVE TAPE (BUMPER) New	690.69 *	3.0*
60	900500	REF *	REFINISH/REPAIR	WHITE PAINTED PIN STRIPE ON FRONT AND RT SIDEExisting	0.00	6.0*
61	936004		ADD'L COST	Shipping	950.00 *	
62	AUTO		ADD'L COST	Paint/Materials	2,925.00 *	
63	AUTO		ADD'L COST	Hazardous Waste Disposal	35.00 *	

\* - Judgment Item

## Estimate Totals

	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
I. Labor Subtotals									
Body	77.5	145.00	0.00	0.00	11,237.50	Y	II. Part Replacement Summary		
Refinish	30.0	145.00	0.00	0.00	4,350.00	Y	Taxable Parts	20,749.93	
							Sales Tax @ 9.250%	1,919.37	
							Total Replacement Parts Amount	22,669.30	
Taxable Labor					15,587.50				
Labor Tax @ 9.250 %					1,441.84				
Labor Summary	107.5				17,029.34				
II. Additional Costs					Amount		IV. Adjustments	Amount	
Taxable Costs					3,910.00		Insurance Deductible	1,000.00	
Sales Tax @ 9.250%					361.68		Customer Responsibility	1,000.00	
Total Additional Costs					4,271.68				
Paint Material Method: Rates									
Init Rate = 100.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
							I. Total Labor:	17,029.34	
							II. Total Replacement Parts:	22,669.30	
							III. Total Additional Costs:	4,271.68	
							Gross Total:	43,970.32	
							IV. Total Adjustments:	1,000.00	
							Net Total:	<del>42,970.32</del>	

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

*John*  
12-16-21

Insurance Co: AR Municipal League  
 Address: P.O. Box 38  
 North Little Rock, AR 72115  
 Telephone: (501) 978-6123

Inspection Date: 6/21/2021

**DISCLAIMER:** This estimate has been prepared by an independent appraisal service. Receipt of this estimate copy from the appraisal service is not an authorization for repairs or a guarantee of payment.

**\*\*\*ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BEFORE REPAIRS BEGIN OR PARTS ARE ORDERED\*\*\*** All supplements will require all parts invoices for the entire repair. Failure to obtain approval may result in the denial of the payment for any and all supplemental repairs.

-Please present this estimate to the shop of your choice

-Only you can authorize repairs to your vehicle

ESTIMATE RECALL NUMBER: 12/15/2021 16:35:54 EA-03790

Mitchell Data Version: OEM: DEC\_21\_V

Alternate Parts: 12/15/2021 16:27:16

Copyright (C) 1994 - 2021 Mitchell International

Software Version: 7.1.242

All Rights Reserved

Date: 12/15/2021 06:27 PM  
Estimate ID: EA-03790  
Estimate Version: 0  
Preliminary  
Profile ID: \* Jonesboro Area

-If the shop has any questions about the estimate or if the shop encounters any supplemental damage, they should contact the appraiser's name listed on this estimate

-Repair time: a good estimate of how long it may take to repair your vehicle is taking the total labor hours and dividing that by 5 (every 5 hours is roughly a repair day). Ex: 28.9 hours / 5 = 5.78 days or 6 days. Add 2 days for a weekend: total repair time @8 days.