

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF	5/26/2022			CASE NUMBER: CE20-3024							
INSPECTION:											
PROPERTY ADDRESS:	1403	1403 OAKHURST									
PROPERTY OWNER: KEVIN L & TONYA LYLES											
OCCUPIED: YES NO X											
BUILDING ELEMENT	1 thru 5 CONDITION					NOTES & COMMENTS					
		VERY POOR				VERY GOOD					
Foundation Type:			2				HOUSE ON PIERS	S. NEEDS			
Piers							LEVELED AND R	REPAIRED			
Solid											
Slab											
Front Porch Type:			2				CONCRETE POR	CH. NEEDS			
Wood							REPAIRED	,			
Concrete											
Exterior Doors and Window	VS	1					MOST WINDOWS	SARE			
Type:							MISSING OR BOA				
Wood								HELD OF			
Vinyl											
Aluminum											
Roof Underlay Type:			2				UNDERLAY APP	EARS TO BE			
OSB/ Plywood							IN NEED OF REP				
1x6							SAGGING IN ARI	· ·			
metal								27.10			
Roof Surface Type: Metal			2				THREE OR MORI	FIAVERS IN			
3-Tab Shingles							NEED OF REPLA				
Dimensional Shingles							TREED OF REFER	CENTERVI			
Chimney							N/A				
Siding Type:		1					OLD WOODEN S	IDING IS			
Wood Lap							BROKEN AND M				
Vinyl							OVER, NEEDS RI				
Masonite							O VER, IVEEDS IN				
Aluminum											
Fascia and Trim Type			2				OLD ROTTED W	OOD NEEDS			
Wood							REPLACED	JOB REEDS			
Vinyl Coil							TEL EL TODO				
Interior Doors Type:			2				NEEDS REPLACE	ED			
Hollow Wood							TELDS REFEREN	115			
Solid Wood											
Interior Walls Type			2				WOOD STUD FR.	AME			
Wood Frame							EXPOSED FROM				
Metal Frame							WALL COVERIN				
Sheetrock							,, ALL COVERIN	•			
Stucco											
Stucco											

Ceilings Type:				2		SHEETROCK NEEDS					
Sheetrock						REPAIRED OT REPLACED					
Stucco											
Ceiling Tile				2		A LITTLE OF FLIFFLYTHING					
Flooring Underlay Type:				2		A LITTLE OF EVERYTHING,					
1x6 center match						NEEDS REPLACED OR					
OSB						REPAIRED, SOME JOIST					
Plywood						MISSING					
Flooring Surfaces Type:			1			NO FLOOR COVERING					
Carpet						THROUGH THE HOUSE					
Linoleum											
Hard Wood											
Vinyl											
Electrical			1			NOT TO CODE					
	Heating		1			NOT TO CODE					
Plumbing			1			NOT TO CODE					
In my opinion, this is 2			XX	is not	not Suitable for human habitation.						
structure											
In my opinion this	XX	is		is not	Physically feasible for rehabilitation.						
structure	7 1 7 1	15		15 Hot	I mysicamy i	custote for foliabilitation.					
In my opinion, this		is	XX	is not	Economical	ly feasible for rehabilitation.					
structure											
In my opinion, this	XX	is		is not	not A public safety hazard and should be condemned						
structure	7	15		Is not	immediately.						
Stractare					minicalatery	, -					
FM	ERGE	INC	V AC'	TION IS	SWARRAN	red. Ves NO XX					
EMERGENCY ACTION IS WARRANTED: YES NO XX HOUSE WAS NOT SECURED AT TIME IF INSPECTION											
HOUSE WAS NOT BEEC	TLD.		111111	11151	Lenon						
Tim Renshaw, Chief Buildin	ıg İnsn	ector				David Cooley, Code Enforcement					
						Zuria Coolej, Code Emorecinent					
Ling Lenden						2					
						_					
Municipal Build	ling, 30	0 Soi	uth Chi	ırch Jone	sboro, Ar./ Pho	ne 870-336-7194/ Fax 870-336-1358					
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											