

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	JUNE 4, 2024 CASE NUMBER: 235985	
PROPERTY ADDRESS:	300 PINE ST.	
PROPERTY OWNER:	MONTGOMERY INVESTMENTS LLC	

The residence is on a pier foundation has shifted. The walls and roof line are sagging due to this. The entire foundation needs to closely inspected and repaired. All trusses must be inspected and any damaged ones replaced. All underlay, tarpaper, and shingles must be replaced. The front porch and rear addition to the home are sagging and pulling away from the main structure. All structural issues must be repaired. All windows and doors are broken, boarded, or missing. All windows and doors must be replaced. The internal walls have been stripped and destroyed due to copper theft. The entire electrical system must be replaced, brought up to current code, and pass inspection. The entire plumbing system must be replaced, brought up to current code, and pass inspection. The siding is very deteriorated and needs repaired or replaced.

CURRENTLY THE HOME IS A HAZARD TO THE HEALTH, WELFARE, AND SAFETY OF THE PUBLIC. THE HOME SHOULD BE RAZED IMMEDIATELY TO ENSURE THE SAFETY OF LOCAL CHILDREN AND OTHER CITIZENS, NOT TO MENTION THE BLIGHT TO THE COMMUNITY.

PROPERTY WAS NOT SECURED AT THE TIME OF INSPECTION.

EMERGENCY ACTION IS WARRANTED: YES NO XX					
In my opinion, this structure	XX	Is		Is not	A public safety hazard and should be condemned immediately.
In my opinion, this structure		Is	XX	Is not	Economically feasible for rehabilitation.
In my opinion, this structure		Is	XX	Is not	Physically feasible for rehabilitation.
In my opinion, this structure		Is	XX	Is not	Suitable for human habitation.

Tim Renshaw, Chief Building Inspector	David Cooley, Code Enforcement		
Level Level	2017		

Municipal Building, 300 South Church Jonesboro, AR/ Phone 870-336-7194/Fax 870-336-1358