

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	2-24-2014	2										
PROPERTY ADDRESS:	1126 Matthews											
PROPERTY OWNER:	Robert Martin											
TROTERT TOWNER.	AND CLE TIRES CHE											
OCCUPIED: YES xx	NO											
CCCCTED. TES AN												
BUILDING ELEMENT	1	thru 5	CONDITI	ON	NOTES & COMMENTS							
	VERY POOR				VERY GOOD							
Foundation Type:	POOR	1	3		GOOD	Turn of Century brick falling in						
Piers/ Brick						Tunn of containing and						
Solid												
Slab												
Front Porch Type:	1	1				Rotten and Busted						
Wood												
Concrete												
Exterior Doors and Windows	1					Broke and Busted						
Type:												
Wood												
Vinyl												
Aluminum	×	v .										
Roof Underlay Type:		2				Rotten shows signs of major dilapidation						
OSB		7/2										
1x6												
metal												
Roof Surface Type:		2				Rotten shows signs of major dilapidation						
3-Tab Shingles												
Dimensional Shingles						N/A						
Chimney		+	-			N/A						
Siding Type:		2				Rotten/ Dilapidated						
Wood Lap												
Vinyl												
Masonite												
Aluminum Fassis and Trim Type		2				Rotten						
Fascia and Trim Type Wood						Rotten						
Vinyl Coil												
Interior Doors Type:	1	1				Non-Existing						
Hollow Wood						Tion Laisting						
Solid Wood												
DOILG WOOG		1	1 1	1		T .						

= = = = = = = = = = = = = = = = = = = =												
Interior Walls Type			1					Ren	noved and dilapidated			
Wood Frame									1			
Metal Frame												
Sheetrock												
Stucco												
Ceilings Type:			1					Ren	noved exposed ceiling joist			
Sheetrock									3			
Stucco												
Ceiling Tile												
Flooring Underlay Type:	Flooring Underlay Type:			2				Weathered				
1x6 center match												
OSB												
Plywood												
Flooring Surfaces Type:				2				Com	pletely dilapidated			
Carpet									1			
Linoleum												
Hard Wood												
Vinyl												
Electrical			1					Not	to code			
eating		1				Not to code			to code			
Plumbing			1			Not to code			to code			
In my opinion, this structure		is	XX	is not	Suitable for human habitation.							
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.							
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.							
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.							
Due to extent of damage struc	ture	sho	uld be	removed	l imm	ediately, r	no work l	nas to	ook place on existing permit and it is			
expired												
EN	MER	GE	NCY	ACTIO	NISV	WARRAN	NTED:	YES	xx NO			
							*					
Tenstoff 2-	24-	-14										
Terry Adams, Certified Building Inspector				Craig	g Dave	nport, Fire	Marshal		Other Signature			
Municipal Bui	lding	, 300	South	Church .	lonesho	oro, Ar./ Ph	one 870-3	36-71	94/ Fax 870-336-1358			
	- 0	,						/ 1				