

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

			1								
DATE OF INSPECTION:	12-15-21										
PROPERTY ADDRESS:	S: 1208 WASHINGTON										
PROPERTY OWNER: CYNTHIA ETAL FLETCHER											
THOI EITH O WITEH.	CINIII		TOILL								
OCCUPIED: YES NO	X										
Geeding. Tes ito	2 1										
BUILDING ELEMENT	1	thru 5 CONI	DITION	NOTES & COMMENTS							
	VERY POOR			VERY GOOD							
Foundation Type:	Took			GGGB	HOUSE IS COMPLETELY						
Piers					DESTROYED BY FIRE. HOUSE						
Solid					WAS NOT SECURED AND IS A						
Slab					HAZARD TO PUBLIC SAFETY						
Front Porch Type:											
Wood											
Concrete											
<b>Exterior Doors and Windows</b>					HOUSE IS OBVIOUSLY BLIGHT TO						
Type:					THE COMMUNITY AND						
Wood					STRUCTUALLY UNSAFE . HOUSE						
Vinyl					SHOULD BE REMOVED						
Aluminum					IMMEDIATELY						
Roof Underlay Type:											
OSB/ Plywood											
1x6											
metal											
Roof Surface Type: Metal											
3-Tab Shingles											
Dimensional Shingles											
Chimney											
Siding Type:											
Wood Lap											
Vinyl											
Masonite											
Aluminum											
Fascia and Trim Type											
Wood											
Vinyl Coil											
Interior Doors Type:											
Hollow Wood											
Solid Wood											

Interior Walls Type										
Wood Frame										
Metal Frame										
Sheetrock										
Stucco										
Ceilings Type:										
Sheetrock										
Stucco										
Ceiling Tile										
Flooring Underlay Type:										
1x6 center match										
OSB										
Plywood										
Flooring Surfaces Type:										
Carpet										
Linoleum										
Hard Wood										
Vinyl										
Electrical										
Heating										
Plumbing										
In my opinion, this structure		is	XX	is not	Suitable for human habitation.					
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.					
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.					
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned					
				immediately.						
	<b>/</b>	<u> </u>	IOT:	OPT 0		7.4.355.55	NIMES :	<b>.</b>	<b>5</b> 0 <b>5</b>	W. MO
							NTED:			
HOUSE WAS NOT SECU	KEL	ΑΊ	TIME	OF IN	SPECI	IION A	IND IS A	. H.	AZA.	RD TO PUBLIC SAFETY
Tim Renshaw, Chief Building								Other Signature		
Tim Lense										
		•								
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358										