

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF	5/31/2022			CASE NUMBER: CE20-7774								
INSPECTION:												
PROPERTY ADDRESS:	1504 DAN	NY										
PROPERTY OWNER:	KEVIN I	. & TO	NYA LYI	LES								
OCCUPIED: YES NO XX												
BUILDING ELEMENT	_	1 thru	5 CONDIT	ION		NOTES & CO	MMENTS					
	VE			VERY								
	PO	OR			GOOD							
Foundation Type:			2			HOUSE ON BLOC						
Piers						FOUNDATION. N						
Solid						LEVELED AND R	EPAIRD					
Slab												
Front Porch Type:			2			CONCRETE. NEE	DS					
Wood						REPAIRED						
Concrete												
Exterior Doors and Window	vs					MOST DOOR AN	D WINDOWS					
Type:						ARE MISSING, BI	ROKEN, OR					
Wood						UNSECURED.						
Vinyl												
Aluminum												
Roof Underlay Type:	1					UNDERLAY APP	EARS TO					
OSB/ Plywood						NEED REPLACIN	G. SAGGING					
1x6						IN AREAS. ROTT	ING ON					
metal						ENDS.						
Roof Surface Type: Metal			2			IN NEED TO REP	LACEMENT					
3-Tab Shingles												
Dimensional Shingles												
Chimney						N/A						
Siding Type:	1					VINYL SIDING IS	BROKEN,					
Wood Lap						MISSING, AND F.						
Vinyl						HOME. NEEDS R	EPLACED					
Masonite												
Aluminum												
Fascia and Trim Type	1					OLD ROTTED WO	OOD NEEDS					
Wood						REPLACED						
Vinyl Coil												
Interior Doors Type:	1					MISSING. NEEDS	REPLACED					
Hollow Wood												
Solid Wood												
Interior Walls Type	1					WOOD STUD FRA	AME					
Wood Frame						EXPOSED FROM	LACK OF					
Metal Frame						WALL COVERING	G					
Sheetrock												

Stucco											
Ceilings Type:			1				WOOD STUD				
Sheetrock							FRAME/RAFTERS EXPOSED				
Stucco							FROM LACK OF CEILING				
Ceiling Tile							COVERING				
Flooring Underlay Type: 1		1				PLYWOOD UNDERLAY.					
1x6 center match							MOST IS MISSING ANY				
OSB						UNDERLAY. EXPOSED					
Plywood							FLOOR JOISTS				
Flooring Surfaces Type:		1					NO FLOOR COVERING				
Carpet							THROUGH THE HOUSE				
Linoleum											
Hard Wood											
Vinyl											
Electrical		1					NOT TO CODE				
Heating		1					NOT TO CODE				
Plumbing		1					NOT TO CODE				
In my opinion, this structure		is	XX	is not	Suitable for human habitation.						
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	XX	is		is not	A public safety hazard and should be condemned immediately.						
						TED: Y	YES NO XX				
HOUSE WAS NOT SECU	JRED .	AT '	TIME	OF INSI	PECTION						
Tim Ranchaw Chief Ruildie	na Inan	octor					David Cooley, Code Enforcement				
Tim Renshaw, Chief Building Inspector						-	David Cooley, Code Elitorcement				
I ming Fenslow							27				
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											