

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## **RESIDENTIAL BUILDING INSPECTION REPORT**

DATE OF INSPECTION:	4-14-17								
PROPERTY ADDRESS:	2303 COURT ST.								
PROPERTY OWNER:	BETTY L. & EDDIE COMBS								
OCCUPIED: YES NO	X								
BUILDING ELEMENT	1	thru 5 (	CONDIT	ION	NOTES	NOTES & COMMENTS			
	VERY POOR			VE GO					
Foundation Type: Piers Solid Slab			3		PIERS HAVE CO AREAS AND NI				
Front Porch Type: Wood Concrete			3		OLD AND WEA REPLACED OR	THERED NEEDS REPAIRED			
Exterior Doors and Windows Type: Wood Vinyl Aluminum		2			WOOD DOORS FRONT AND BO BACK , NEEDS REPAIRED				
Roof Underlay Type: OSB/ Plywood 1x6 metal			3			PE BUT SEEMED TO APE FOR AGE OF			
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles			3		THREE TAB SH SHAPE	INGLES IN FAIR			
Chimney Siding Type: Wood Lap Vinyl Masonite Aluminum		2				E SIDING OLD AND VEEDS REPAIRED IN VINT			
Fascia and Trim Type Wood Vinyl Coil		2			SAME AS SIDIN	IG			
Interior Doors Type: Hollow Wood Solid Wood		2			WILL NOT OPE TO SHIFTING C	N OR CLOSE DUE DF FLOORS			

Interior Walls Type					2	WOOD FRAMED WALLS IN FAIR			
Wood Frame					3	SHAPE			
Metal Frame									
Sheetrock									
Stucco									
Ceilings Type:					3	NEEDS REPAIRED OR REPLACED			
Sheetrock						IN SOME AREAS DUE TO WATER			
Stucco						DAMAGE			
Ceiling Tile									
Flooring Underlay Type:						NEEDS REPAIRED OR REPLACED			
1x6 center match						IN SOME AREAS			
OSB					3				
Plywood					J				
Flooring Surfaces Type:						MIOXED FLOOR COVERINGS ALL			
Carpet						NEED REPLACED			
Linoleum				2					
Hard Wood									
Vinyl									
Electrical				2		NOT TO CODE			
Heating				2		NOT TO CODE			
Plumbing				2		NOT TO CODE			
<u> </u>									
In my opinion, this structure		is	X	is not	Suit	able for human habitation.			
			Λ	18 1101					
In my opinion this structure		is	Χ	is not	Physically feasible for rehabilitation.				
In my opinion, this structure		is	Χ	is not	Economically feasible for rehabilitation.				
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.				
· · ·									
EMERGENCY ACTION IS WARRANTED: YES X NO									
ŀ	IOUS	SE V	VAS I	NOT SE	CURE	ED AT TIME OF INSPECTION			
Tim Renshaw, Chief Building Inspector						Other Signature			
Tim Remol									
1 mm Mercor	~~~								
Municipal Bu	ilding	. 300	South	Church	Jonesb	oro, Ar./ Phone 870-336-7194/ Fax 870-336-1358			