

City of Jonesboro

300 S. Church Street Jonesboro, AR 72401

Signature Copy

Ordinance: O-EN-002-2021

File Number: ORD-21:003 Enactment Number: O-EN-002-2021

AN ORDINANCE DECLARING AN EXCEPTIONAL SITUATION AND WAIVING THE REQUIREMENTS OF COMPETITIVE BIDDING FOR TRUCK BODY WORK ON A WRECKED STREET DEPARTMENT GRAVEL TRUCK, AND DECLARING AN EMERGENCY

WHEREAS, the Street Department's 2014 Mack 14 yard gravel truck was damaged in an accident on November 13, 2020; and,

WHEREAS, the City's insurance company (Arkansas Municipal League Vehicle Program) appraiser handled the transactions to their rules and regulations; and,

WHEREAS, the City has contacted "The Body Shop" for an estimate, and they and the city's insurance company has agreed on the work to be done for \$70,468.88; and,

WHEREAS, the city's insurance company has already paid the City \$69,468.88 on January 14, 2021, which represents the repair cost less \$1,000 deductible; and,

WHEREAS, The Body Shop is the local company chosen by the adjuster that has the capability and expertise in the repair of this type of equipment, and has the ability to complete the work in a timely manner.

NOW THEREFORE, BE IT ORDAINED BY THE CITY COUNCIL OF THE CITY OF JONESBORO THAT:

Section 1: An exceptional situation as described above exists so that competitive bidding requirements are hereby waived.

Section 2: Said expense will be paid from the insurance recovery monies which was paid by Arkansas Municipal League Vehicle Program to fund the repairs plus the deductible.

Section 3: The City Council further finds and declares that an emergency exists due to public safety concerns as the damaged equipment needs to be operational quickly, and this Ordinance being necessary for the repairs shall take effect and be in full force and effect from and after its passage and approval.

PASSED AND APPROVED THIS 2ND DAY OF FEBRUARY, 2021.

File Number: ORD-21:003 Enactment Number: O-EN-002-2021

Date: 12/31/2020 07:22 PM

Estimate ID: EA-02797

Estimate Version: Preliminary

Profile ID: * Jonesboro Area

Arkansas Municipal League

Vehicle Program P.O. Box 38, North Little Rock, AR 72115

Damage Assessed By: Keith Selby

Supplements To: Kelth Selby (kelth@eclipseappraisal.com)or Call

(870) 273-6497

Type of Loss: Collision

Deductible: 1,000,00

Classification: Field

Condition Code: Good

Date of Loss: 11/13/2020

Payer: Insurance

File Number:

EA-02797

Claim Number: 20-00990-001

Insured: City of Jonesboro Owner: City of Jonesboro

Address: PO Box 1845, Jonesboro, AR 72403

Telephone: Home Phone:

(870) 932-0740

Mitchell Service: 911000

Description: 14 GU713 Mack Granite 1M2AX09C2EM019676

VIN:

Mileage: 78,000

DEMIALT:

Parts Profile:

Jonesboro Area

Color: White Parts Profile Version: ' 2

Line	Entry Number		Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	REMOVE/REPLACE	Headlamp Assembly, Lft	New	259.52 *	0.0*
2	900500	BDY *	REMOVE/REPLACE	Hood Shell	New	3,937.56 *	9.0*
3		REF	REFINISH/REPAIR	Hood Shell		19 + 20 € 10 Sept 20 42 10 Sept 20 40 10 Sept 20 50 Sept 20 Sept 20 50 Sept	8.0*
4	900500	BDY *	REMOVE/REPLACE	Front Fender Flare, Lft	New	241.01 *	1.4*
5	900500	BDY *	REMOVE/REPLACE	Left Lower Step	New	119.93 *	0.2*
6	900500	BDY *	REMOVE/REPLACE	Cab Shell	Qual Recycled Part	10,000.00	
7				Includes R & I Complete Interior	recting sucting cultion of the constraint of the		
8		REF	REFINISHIREPAIR	Cab Shell			18.5*
9	900500	BDY *	REMOVE/REPLACE	Door Mirror Assembly, Lft .	New	695.62 *	0.8*
10	900500	BDY *	REMOVE/REPLACE	Left Rear Outer Wheel, Front Axle	Sublet	245.00 *	0.04
11	900500	BDY *	REMOVE/REPLACE	Left Rear Outer Wheel, Rear Axle	Sublet	245.00 *	0.0*
12	900500	BDY *	REPAIR	Left Bedside	Existing		10.0*
13		REF	REFINISH/REPAIR	Left Bedside			*0.8
14	900500	BDY .	REMOVE/REPLACE	Tarp Pivot, Lft .	New	145.00 *	2.0"
16	900500	BDY *	REPAIR	Left Fuel Tank	Existing		2.5*
16	900600	BDY *	REMOVE/REPLACE	Antifreeze	New	126.00 *	0.0*
17	931061	MCH*	ADD'L LABOR OP	Evacuate & Recharge	Existing		1.4"
18	936018		ADD'L COST	R134A Freon & Oil		40.00 *	
19	900500	MCH *	ADD'L LABOR OP	Alm Headlamps	Existing		0.5*
20	900500	MCH*	REMOVE/REPLACE	Engine Assembly	Sublet	36,214,64 *	0.0*
21				Sublet to Tri-State Truck Center		52 N T T T T T T T T T T T T T T T T T T	
22				Engine ran for an extended period of time laying			

ESTIMATE RECALL NUMBER: 12/31/2020 18:44:02 EA-02797

Mitchell Data Version: OEM: DEC_20_V

Alternate Parts: 12/31/2020 18:54:59

Copyright (C) 1994 - 2020 Mitchell International

Software Version: 7.1.239

All Rights Reserved

Page 1 of 3

Date: 12/31/2020 07:22 PM

Estimate ID: EA-02797 Estimate Version: 0

Preliminary

Profile ID: * Jonesboro Area

23 24

28

AUTO

25 26 900500 BDY * REMOVE/REPLACE 27 AUTO ADD'L COST

on its side and caused extensive internal damage. Extensive search for an ikq engine with 78k or

less miles was unsuccessfull Top off Trans & Hydraulic Fluids

Paint/Materials Hazardous Waste Disposal New

200.00 * 0.0* 1,662,60 *

5.00 *

* - Judgment Item

ADD'L COST

Estimate Totals

I.	Labor Subtotals Body Rofinish Mechanical	Units 75.9 34.5 1.9	75.00 75.00 75.00	Add'I Labor Amount 0.00 0.00	Sublet Amount 0.00 0.00 0.00	Totals 5,692.50 2,587.50 142.50		Part Replacement Summary Taxable Parts Parts Adjustments Sales Tax	g 8.500%	Amount 52,428,28 2,500.00 4,668.90	
		Taxable Labor Labor Tax		@ 8.500 %		8,422.50 716.91		Total Replacement Parts Amount		59,597.18	
	Labor Summary	112.3				9,138.41					
111.	Additional Costs Taxable Costs	Sales Tax		@ 4	9.500%	Amount 1,597.50 135.79	IV.	Adjustments Insurance Deductible		Amount 1,000.00-	
	Total Additional Costs					1,733.29		Customer Responsibility 1,			
Paint Material Method: Rates Init Rate = 45.00 , init Max Hours = 99.9, Addi Rate = 0.00											
	-		·	-			L. . ~II. ; III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total:	Amort to me	9,138.41 59,597.18 1,733.29 70,468.88	
							IV.	Total Adjustments: Net Total:		1,000.00- 69,468.88	

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

13 Rollover (P)

ESTIMATE RECALL NUMBER: 12/31/2020 18:44:02 EA-02797

Mitchell Data Version: OEM: DEC_20_V

Alternato Parts: 12/31/2020 18:54:59

Software Version:

7.1.239

Copyright (C) 1994 - 2020 Mitchell International All Rights Reserved

Page 2 of 3

Date: 12/31/2020 07:22 PM

Estimate ID: EA-02797

Estimate Version: 0 Preliminary

Profile ID: * Jonesboro Area

Insurance Co: AR Municipal League

Address: P.O. Box 38

North Little Rock, AR 72115

Telephone: (501) 978-6123

Body Shop: The Body Shop Auto & Heavy Truck Repair, LLC

Address: 224 Harry Dr

Bono, AR 72416

Telephone: (870) 934-1633 Fax Phone: (870) 934-1634

DISCLAIMER: This estimate has been prepared by an independent appraisal service. Receipt of this estimate copy from the appraisal service is not an authorization for repairs or a guarantee of payment.

ALL SUPPLEMENTS REQUIRE PRIOR-APPROVAL-BEFORE REPAIRS BEGIN OR-PARTS ARE ORDERED All supplements will require all parts invoices for the entire repair. Failure to obtain approval may result in the denial of the payment for any and all supplemental repairs.

ESTIMATE RECALL NUMBER: 12/31/2020 18:44:02 EA-02797

Mitchell Data Version: OEM: DEC_20_V

Alternate Parts: 12/31/2020 18:54:59

Software Version:

7.1,239

Copyright (C) 1994 - 2020 Mitchell International All Rights Reserved

Page 3 of 3