

Date: 12/31/2020 07:22 PM
 Estimate ID: EA-02797
 Estimate Version: 0
 Preliminary
 Profile ID: * Jonesboro Area

Arkansas Municipal League

Vehicle Program P.O. Box 38, North Little Rock, AR 72115

Damage Assessed By: Keith Selby

Supplements To: Keith Selby (keith@eclipseappraisal.com) or Call
 (870) 273-6497

Classification: Field

Condition Code: Good
 Date of Loss: 11/13/2020
 Payer: Insurance
 File Number: EA-02797
 Claim Number: 20-00990-001

Type of Loss: Collision

Deductible: 1,000.00

Insured: City of Jonesboro
 Owner: City of Jonesboro
 Address: PO Box 1845, Jonesboro, AR 72403
 Telephone: Home Phone: (870) 932-0740

Mitchell Service: 911000

Description: 14 GU713 Mack Granite
 VIN: 1M2AX09C2EM019676
 Mileage: 78,000
 OEM/ALT: A
 Parts Profile: Jonesboro Area
 Color: White

Parts Profile Version: 2

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	REMOVE/REPLACE	Headlamp Assembly, Lft	New	259.52 *	0.0*
2	900500	BDY *	REMOVE/REPLACE	Hood Shell	New	3,937.56 *	9.0*
3		REF	REFINISH/REPAIR	Hood Shell			8.0*
4	900500	BDY *	REMOVE/REPLACE	Front Fender Flare, Lft	New	241.01 *	1.4*
5	900500	BDY *	REMOVE/REPLACE	Left Lower Step	New	119.93 *	0.2*
6	900500	BDY *	REMOVE/REPLACE	Cab Shell	Qual Recycled Part	10,000.00 *	50.0*
7				Includes R & I Complete Interior			
8		REF	REFINISH/REPAIR	Cab Shell			18.5*
9	900500	BDY *	REMOVE/REPLACE	Door Mirror Assembly, Lft	New	695.62 *	0.8*
10	900500	BDY *	REMOVE/REPLACE	Left Rear Outer Wheel, Front Axle	Sublet	245.00 *	0.0*
11	900500	BDY *	REMOVE/REPLACE	Left Rear Outer Wheel, Rear Axle	Sublet	245.00 *	0.0*
12	900500	BDY *	REPAIR	Left Bedside	Existing		10.0*
13		REF	REFINISH/REPAIR	Left Bedside			8.0*
14	900500	BDY *	REMOVE/REPLACE	Tarp Pivot, Lft	New	145.00 *	2.0*
15	900500	BDY *	REPAIR	Left Fuel Tank	Existing		2.5*
16	900500	BDY *	REMOVE/REPLACE	Antifreeze	New	126.00 *	0.0*
17	931061	MCH *	ADD'L LABOR OP	Evacuate & Recharge	Existing		1.4*
18	936018		ADD'L COST	R134A Freon & Oil		40.00 *	
19	900500	MCH *	ADD'L LABOR OP	Alm Headlamps	Existing		0.5*
20	900500	MCH *	REMOVE/REPLACE	Engine Assembly	Sublet	36,214.64 *	0.0*
21				Sublet to Tri-State Truck Center			
22				Engine ran for an extended period of time laying			

ESTIMATE RECALL NUMBER: 12/31/2020 18:44:02 EA-02797

Mitchell Data Version: OEM: DEC_20_V

Alternate Parts: 12/31/2020 18:54:59

Copyright (C) 1994 - 2020 Mitchell International

Page 1 of 3

Software Version: 7.1.239

All Rights Reserved

Date: 12/31/2020 07:22 PM
Estimate ID: EA-02797
Estimate Version: 0
Preliminary
Profile ID: * Jonesboro Area

Insurance Co: AR Municipal League
Address: P.O. Box 38
North Little Rock, AR 72115
Telephone: (501) 978-6123

Body Shop: The Body Shop Auto & Heavy Truck Repair, LLC
Address: 224 Harry Dr
Bono, AR 72416
Telephone: (870) 934-1633
Fax Phone: (870) 934-1634

DISCLAIMER: This estimate has been prepared by an independent appraisal service. Receipt of this estimate copy from the appraisal service is not an authorization for repairs or a guarantee of payment.

*****ALL SUPPLEMENTS REQUIRE PRIOR-APPROVAL-BEFORE REPAIRS BEGIN OR PARTS ARE ORDERED***** All supplements will require all parts invoices for the entire repair. Failure to obtain approval may result in the denial of the payment for any and all supplemental repairs.

ESTIMATE RECALL NUMBER: 12/31/2020 18:44:02 EA-02797

Mitchell Data Version: OEM: DEC_20_V

Alternate Parts: 12/31/2020 18:54:59

Copyright (C) 1994 - 2020 Mitchell International
All Rights Reserved

Software Version: 7.1.239

Page 3 of 3