

My commission expires: _

TTJD Investments LLC 3108 Woodsprings Rd Jonesboro, AR 72404
Jonesboro, AR 72404
RE: 3206 Fairview Jonesboro, AR 72401
I, Michael McQuay, a Code Enforcement Officer, being duly sworn upon oath, that I served the attached notice(s) upon each of the persons or firms therein addressed, by depositing copies thereof in the United States Mail, enclosed within envelopes plainly addressed, as shown with postage fully prepaid, at the Jonesboro, Arkansas Post Office located at 310 East Street, Suite A., before 3:00 P.M., on the
Michael McQuay Jonesboro Code Enforcement
Subscribed and sworn to before me the 23rd day of August, 2022.
Som Motal Notary Public ARKANSAS ARKANSAS



Notice of Violation

Date: 08/22/2022

TTJD Investments LLC 3108 WOODSPRINGS RD Jonesboro, AR 72404

SUBJECT: 3206 FAIRVIEW JONESBORO, AR 72401

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley

Code Enforcement Officer P.O. Box 1845 Jonesboro, AR 72403

CE20-5979

Sign if served in person

Code Enforcement Officer Signature, if delivered in person

Property Owner/Interested Party Signature, if delivered in



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	AUC	GUST 12, 2022			CAS	CASE NUMBER: CE20-5979			
PROPERTY ADDRESS:	3200	06 FAIRVIEW							
PROPERTY OWNER:				TO I					
0.00	O XX	D INVES	SIMEN	NIS LI	LC				
BUILDING ELEMENT									
							NOTES & COMN	1ENTS	
		VERY POOR				VERY GOOD			
Foundation Type:			2			GOOD	FOUNDATION IS CRAC	KED IN	
Piers							MANY PLACED. HAS SI	EPERATED	
Solid							FROM EXTEROR BRICK	AROUND	
Slab							ENTIRE HOME. NEEDS	REPAIRED	
Front Porch Type:				3			CONCRETE IN FAIR	SHAPE	
Wood							The second secon	. SIM L	
Concrete									
Exterior Doors and Window	'S		2				MOST ARE BROKEN	J OR	
Type:							BOARDED. ALL HA		
Wood							SEVERE SMOKE DA		
Vinyl							ALL NEED REPLAC		
Aluminum									
Roof Underlay Type:			2				UNDERLAY WHERE	EFIRE	
OSB/ Plywood	nderlay Type: ywood						WAS IS DAMAGED		
1x6							NEEDS REPLACED.		
metal									
Roof Surface Type: Metal			2				SHINGLES ARE OLD	AND	
3-Tab Shingles							DAMAGED. MUST B	E	
Dimensional Shingles							REPLACED		
Chimney							N/A		
Siding Type:			2				BRICK AND WOOD SIDI	NG WOOD	
Wood Lap							SIDING IS BROKEN, MIS	SING	
Vinyl				- 1			AND/OR FALLING OFF. I EXTERIOR HAS SOME C		
Masonite							BRICK NEEDS REPAIRED	D AND	
Aluminum							WOOD NEEDS REPLACE	ED.	
Fascia and Trim Type			2				FASICIA AND TRIM	ARE	
Wood Vinal Cail							ROTTEN AND FALLI	NG OFF.	
Vinyl Coil							NEEDS REPLACED		
Interior Doors Type: Hollow Wood		1					BROKEN, MISSING (
Solid Wood							BURNED UP. ALL NE	EED	
		1					REPLACED		
Interior Walls Type Wood Frame		1					SHEETROCK WALLS V		
Metal Frame							HOLES, SMOKE, AND		
Sheetrock							DAMAGE THROUGHO		
Sneetrock Stucco							HOME. STUDS DAMAC FIRE AREA NEED REPI		
Stucco							ALL SHEETROCK REP		

Ceilings Type:		T	1	T	CHEETE OOK OF THE		
Sheetrock			•		SHEETROCK CEILINGS.		
Stucco					HOLES, MISSING, SMOKE		
Ceiling Tile					AND WATER DAMAGE		
coming the					THROUGHOUT. ALL NEEDS		
Flooring Underlow True		-	1		REPLACED		
1x6 center match	Flooring Underlay Type:		1		PLYWOOD UNDERLAY HAS		
OSB					SMOKE WATER, AND/OR		
				- 1	FIRE DAMAGE. 2 ND FLOOR IS		
Plywood					NOT SAFE TO WALK ON.		
Di c c m		3			MUST BE REPLACED		
Flooring Surfaces Type:			1		ALL FLOOR COVERING HAS		
Carpet		1			SMOKE NEEDS REPLACED		
Linoleum							
Hard Wood							
Vinyl							
Electrical					NOT TO CODE		
Heating					NOT TO CODE		
Plumbing					NOT TO CODE		
					THOT TO CODE		
In my opinion, this	1	is	XX	is not	Suitable for human habitation.		
structure		6					
In my opinion this		is	XX	is not	Physically feasible for rehabilitation.		
structure							
In my opinion, this structure		is	XX	is not	Economically feasible for rehabilitation.		
In my opinion, this	3737						
structure	XX	is		is not	A public safety hazard and should be condemned immediately.		
FM	FDCE	NC	VAC	FION 16	SWADDANGED NEG NO W		
HOME WAS NOT SECU	RE AT	1110	I AC	TON IS	WARRANTED: YES NO XX		
Tim Renshaw, Chief Building Inspector					David Cooley, Code Enforcement		
Tim Lenston					Toly.		
Municipal Build	ing. 300) Sou	ıth Chu	rch Jones	boro, Ar./ Phone 870-336-7194/ Fax 870-336-1358		
	-6, -0,	200	- Chu	. on oones	2010, 21.7 1 HORE 0 / U-23U- / 194/ FAX 8 / U-23U-1328		

CERTIFIED MAIL® RECEIPT

Domestic Mail Only

For delivery information, visit our website at www.usps.com

Certifled Mail Fee

Extra Services & Fees (check box, add fee as information)

Return Receipt (electronic)

Return Receipt (electronic)

Certifled Mail Restricted Delivery

Adult Signature Restricted Delivery

Postage

Sent To

Siteet and Apt, No. or BO Box No.

City, State, Zigna Services AR

Tayoy

PS Form 9800, April 2015 PSE/Sconocomes and Sec Reverse for Instructions