

My commission expires:

AFFIL	AVII
James + Jessy Harre	.11
Brookland, AR 72417	7
RE: 1301 Huntington J	Tonesboro, AR 72401
I, Michael McQuay, a Code Enforcement Officer attached notice(s) upon each of the persons or firm	, being duly sworn upon oath, that I served the ms therein addressed, by depositing copies
thereof in the United States Mail, enclosed within	envelopes plainly addressed, as shown with
postage fully prepaid, at the Jonesboro, Arkansas	Post Office located at 310 East Street, Suite A.,
before 3:00 P.M., on the 15th day of 5e	Hember, 2022.
į.	
	Michael McQuay Jonesboro Code Enforcement
Subscribed and sworn to before me the15 th d	ay of <u>September</u> , <u>2022</u> .
Notary Public	ARKANSAS
s to aligne	1 .a £ 8

May 20, 2032



Notice of Violation

Date: 09/15/2022

James & Jessy Harrell 562 CR 765

Brookland, AR 72417 Mobile: 870-919-1128

SUBJECT: 1301 HUNTINGTON JONESBORO, AR 72401

According to county records, you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Sincerely,

David Cooley Code Enforcement Officer P.O. Box 1845 Jonesboro, AR 72403

CE22-1004

Sign if served in person

Code Enforcement Officer Signature, if delivered in person

Property Owner/Interested Party Signature, if delivered in person



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	SEPTEMBER 15, 2022	CASE NUMBER: CE22-1004
PROPERTY ADDRESS:	1301 HUNTINGTON AVE.	
PROPERTY OWNER:	JAMES W & JESSY T HAR	RELL

THE HOME IS ON PIER FOUNDATION. THE FRONT PORCH IS PLYWOOD WHICH IS CURLING AND SAGGING IN PLACES. THE PORCH IS ALSO SOFT AND FEELS UNSAFE IN PLACES. THE EXTERIOR IS A MIXTURE OF SIDING. THE SILL PLATE ON THE NORTHEAST CORNER OF THE HOME IS EXPOSED AND ROTTING. THE SILL PLATE NEEDS TO BE REAPIRED OR REPLACED. THE INTERIOR FLOOR HAS ELEVATION CHANGES, WHICH COULD MEAN DAMAGED FLOOR JOISTS. ALL JOISTS NEED TO BE INSPECTED, REPAIRED, AND/OR REPLACED AS NEEDED. THE FLOOR UNDERLAY ALSO NEEDS REPAIRED AND/OR REPLACED. MUCH OF THE WALLS AND CEILING HAVE HAD THE PLASTER REMOVED EXPOSING THE STUDS, SLATS, AND ELECTRICAL. THERE HAS BEEN SOME PLUMBING WORK DONE WITHOUT PERMITS AND A STOP WORK ORDER WAS PREVIOUSLY POSTED. THE ROOF IS SAGGING. UNDERLAY AND SHINGLES NEED REPLACED. SOME OF THE WINDOWS ARE BROKEN AND MUST BE REPAIRED OR REPLACED. THERE IS GRAFFITI INSIDE THE HOME DUE TO IT BEING UNSECURED. THE SECOND FLOOR WAS NOT FULLY INSPECTED DUE TO MISSING FLOOR AND SAFETY CONCERNS. THE HOME MUST BE RAZED OR REPAIRED, WITH PROPER PERMITS, IMMEDIATELY TO ENSURE THE SAFETY OF LOCAL CHILDREN AND OTHER CITIZENS, NOT TO MENTION THE BLIGHT TO THE COMMUNITY.

PROPERTY WAS NOT SECURED AT THE TIME OF INSPECTION.

In my opinion, this structure		Is	XX	Is not	Suitable for human habitation.
In my opinion, this structure	XX	Is		Is not	Physically feasible for rehabilitation.
In my opinion, this structure		Is	XX	Is not	Economically feasible for rehabilitation.
In my opinion, this structure	XX	Is		Is not	A public safety hazard and should be condemned immediately.

EMERGENCY ACTION IS WARRANTED: YES NO XX

Tim Renshaw, Chief Building Inspector	David Cooley, Code Enforcement		
Tim Lend	Toly		

Municipal Building, 300 South Church Jonesboro, AR/ Phone 870-336-7194/Fax 870-336-1358

