

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	5-13-16											
PROPERTY ADDRESS:	1207 FRENCH											
PROPERTY OWNER:	DUWAYNE VETETO ETAL											
OCCUPIED: YES NO	K											
BUILDING ELEMENT	1	thru 5 (CONDIT	ION		NOTES & COMMENTS						
BOILDING ELEMENT		Till a S	I	1011	VEDV	TOTES & COMMENTS						
	VERY POOR				VERY GOOD							
Foundation Type:						MOBILE HOME ON PIERS, IN BAD						
Piers	5					SHAPE						
Solid												
Slab												
Front Porch Type:						WOODEN PORCH IN BAD SHAPE						
Wood		4				,ROTTED AND FALLING DOWN						
Concrete												
Exterior Doors and Windows						METAL MOBILE HOME DOORS,						
Type:		4				ROTTED AND WEATHERED						
Wood						WATER DAMAGED						
Vinyl												
Aluminum												
Roof Underlay Type:						OLD ROOF, MOBILE HOME ROOF						
OSB/ Plywood												
1x6			3									
metal			3									
Roof Surface Type: Metal						MOBILE HOME ROOF						
3-Tab Shingles												
Dimensional Shingles												
Chimney						N/A						
Siding Type:						OLD METAL SIDING, WEATHERED						
Wood Lap						AND NEEDS REPLACED OR						
Vinyl						PAINTED						
Masonite			3									
Aluminum												
Fascia and Trim Type						N/A						
Wood												
Vinyl Coil												
Interior Doors Type:						HOLLOW DOORS IN BAD SHAPE,						
Hollow Wood						NEEDS REPLACED						
Solid Wood												

Interior Walls Type								WEA	THERED AND ROTTED, NEEDS		
Wood Frame				4					ACED		
Metal Frame								KLII	LACED		
Sheetrock											
Stucco											
Ceilings Type:								SHEE	ETROCK CEILINGS NEED		
Sheetrock				4					LACED		
Stucco								KLII	DACED		
Ceiling Tile											
Flooring Underlay Type:								OSB	UNDERLAY FALLING IN AND		
1x6 center match									TED THROUGHOUT THE HOME		
OSB			5					KOT	TED THROUGHOUT THE HOME		
Plywood											
Flooring Surfaces Type:								OI D	CARPET AND LINOLEUM		
Carpet				4					DS REPLACED		
Linoleum								INLLI			
Hard Wood											
Vinyl											
Electrical			5					NOT	TO CODE		
Heating		5							TO CODE		
Plumbing		5				NOT TO CODE					
Tramonig								1,01	10 0022		
In my opinion, this structure		is	X	is not	Suita	Suitable for human habit			n.		
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
							-		-		
							RANTED				
HC	OUS	E W	AS N	NOT SE	CURE	D AT T	IME OF	INSPE	CTION		
Tim Renshaw, Chief Building Inspector									Other Signature		
Times Level											
			-								
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											