

## DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

## **RESIDENTIAL BUILDING INSPECTION REPORT**

DATE OF INSPECTION:	9-22-16										
PROPERTY ADDRESS:	916 OLD PARAGO										
PROPERTY OWNER:	DENNIS AND JAN										
OCCUPIED: YES NO X											
BUILDING ELEMENT	1 thru 5 C	CONDITION	NOTES & COMMENTS								
	VERY	VERY	1								
Francisco de Cara a Transia	POOR	GOOD									
Foundation Type: Piers			HOUSE IS COMPLETELY DESTROYED BY FIRE								
Solid			DESTROTED BT FIRE								
Slab											
Front Porch Type:			HOUSE IS COMPLETELY								
Wood			DESTROYED BY FIRE								
Concrete											
Exterior Doors and Windows			HOUSE IS COMPLETELY								
Туре:			DESTROYED BY FIRE								
Wood											
Vinyl											
Aluminum											
Roof Underlay Type:			HOUSE IS COMPLETELY								
OSB/ Plywood			DESTROYED BY FIRE								
1x6											
metal											
Roof Surface Type: Metal			HOUSE IS COMPLETELY								
3-Tab Shingles			DESTROYED BY FIRE								
Dimensional Shingles											
Chimney											
Siding Type:			HOUSE IS COMPLETELY								
Wood Lap			DESTROYED BY FIRE								
Vinyl											
Masonite											
Aluminum											
Fascia and Trim Type			HOUSE IS COMPLETELY								
Wood Vinul Cail			DESTROYED BY FIRE								
Vinyl Coil			HOUSE IS COMPLETELY								
Interior Doors Type: Hollow Wood			HOUSE IS COMPLETELY DESTROYED BY FIRE								
Solid Wood											

		1		· · ·			1	-		
Interior Walls Type										SE IS COMPLETELY
Wood Frame								DE	EST	ROYED BY FIRE
Metal Frame										
Sheetrock										
Stucco										
Ceilings Type:								HC	DUS	SE IS COMPLETELY
Sheetrock								DE	EST	ROYED BY FIRE
Stucco										
Ceiling Tile										
Flooring Underlay Type:								HC	)US	SE IS COMPLETELY
1x6 center match								DE	EST	ROYED BY FIRE
OSB										
Plywood										
Flooring Surfaces Type:								HC	)US	SE IS COMPLETELY
Carpet								DE	EST	ROYED BY FIRE
Linoleum										
Hard Wood										
Vinyl										
Electrical								DE	EST	ROYED
Heating							DE	EST	ROYED	
Plumbing					DESTROYED				ROYED	
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~										
In my opinion, this structure		is	Χ	is not	Suita	able for	human h	abita	tio	n.
In my opinion this structure	-	is	X	is not	Physically feasible for rehabilitation.					
	<b> </b>									
In my opinion, this structure	<u> </u>	is	Χ	is not	Economically feasible for rehabilitation.					
In my opinion, this structure	Х	is		is not	A public safety hazard and should be condemned immediately.					
									_ ~	
Ŀ	ME	RGE	ENCY	ACTIC	<u>)N IS</u>	WAR	RANTED	): Y	ES	X NO
				1					<del>.</del>	I.
	<u>_</u>								_	
Tim Renshaw, Chief Building Inspector										Other Signature
Tim Rense										
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358										
	nume		JUUU	і улиген.	IUHESD(	ло. АГ./	1 HUHE 0/U		•/17	(+/ FAX 0/V-JJV-1JJ0