

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	5-13-16											
PROPERTY ADDRESS:	904 BELT											
PROPERTY OWNER:	MABRY PROPERTIES & HOLDINGS											
				<u> </u>		1						
OCCUPIED: YES NO X	Κ											
BUILDING ELEMENT	1	thru 5 (CONDIT	ION		NOTES & COMMENTS						
DOLDER VO BERVER VI	VERY		1	1011	VERY	THO TES & CONTINUE VIS						
	POOR				GOOD							
Foundation Type:	1					PIERS ,JOIST FALLING OFF						
Piers						PIERS,NEEDS REPAIRED						
Solid												
Slab												
Front Porch Type:	1					SLAB ON FRONT, WOODEN IN						
Wood						BACK I,ROTTED AND FALLING						
Concrete												
Exterior Doors and Windows		2				WINDOWS ARE SECURE ,FRONT						
Type:						DOORIS SECURED ,BACK DOOR						
Wood						OFF HINGES						
Vinyl												
Aluminum												
Roof Underlay Type:			2			ROOF SAGGING BETWEEN						
OSB/ Plywood			3			FAFTERS						
1x6												
metal												
Roof Surface Type: Metal						SHINGLES NEEDS REPLACED						
3-Tab Shingles		2				WITH DECKING						
Dimensional Shingles												
Chimney						N/A						
Siding Type:						NEDDS PAINTING IN SOME AREAS						
Wood Lap			3			AND REPAIRED						
Vinyl												
Masonite												
Aluminum												
Fascia and Trim Type						ALL FASCIA IS ROTTED OR						
Wood		2				MISSING ,NEEDS REPLACED						
Vinyl Coil												
Interior Doors Type:						MISSING OR NEEDS REPLACED						
Hollow Wood		2										
Solid Wood												

Interior Walls Type				2					ETROCK,PANELING, IN BAD		
Wood Frame									PE ,HOLES, IN SOME ROOMS		
Metal Frame								MISS	JING		
Sheetrock											
Stucco		<u> </u>									
Ceilings Type:			1					WAT	ER DAMAGED FROM LEAKS		
Sheetrock			1								
Stucco											
Ceiling Tile		<u> </u>									
Flooring Underlay Type:			1						ES IN FLOORS , AND ROTTED		
1x6 center match			1					FLO	ORS THROUGHOUT		
OSB											
Plywood											
Flooring Surfaces Type:								N/A			
Carpet			1								
Linoleum											
Hard Wood											
Vinyl											
Electrical		1							TO CODE		
Heating		1				NOT TO CODE					
Plumbing		1				NOT TO CODE			TO CODE		
In my opinion, this structure		is	X	is not	Suita	able for	human h	abitatio	n.		
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
							ANTED:				
НС)ME	WA	S NO	OT SEC	URED	AT TI	ME OF I	NSPEC	CTION		
Tim Renshaw, Chief Building I	Inche	ctor	_						Other Signature		
Tim Kenshaw, Chief Dunding	+						Other Signature				
Imany Ferral											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											