

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	4-14-17						
PROPERTY ADDRESS:	4719 INDUS	TRIAL I	DR.				
PROPERTY OWNER:	ROBERT &	LOUET	TA GUY				
OCCUPIED: YES NO	XX						
BUILDING ELEMENT	1	thru 5 CO	NDITION		NOTES & COMMENTS		
BUILDING ELEMENT	.	unu s CO	NDITION	T	TOTAL COMMENTS		
	VERY POOR			VERY GOOD			
Foundation Type:					MOBILE HOME ON PIERS		
Piers		2					
Solid							
Slab							
Front Porch Type:					WOODEN PORCH IN BAD SHAPE		
Wood	1				NEEDS REMOVED AND REPLACED		
Concrete							
Exterior Doors and Windows					ALL DOORS AND WINDOWS ARE		
Type:		2			GONE ON THE REAR OF TRAILER		
Wood							
Vinyl							
Aluminum							
Roof Underlay Type:					PITCHED ROOF WITH SHINGLES,		
OSB/ Plywood	1				NEEDS REPLACED		
1x6							
metal							
Roof Surface Type: Metal					DAMAGED ALL OVER NEEDS		
3-Tab Shingles	1				REPLACED		
Dimensional Shingles							
Chimney					N/A		
Siding Type:					SIDING IN FAIR SHAPE ON FRONT,		
Wood Lap					ALL IS DAMAGED OR GONE ON		
Vinyl		2			REAR OF TRAILER		
Masonite							
Aluminum							
Fascia and Trim Type					SAME AS SIDING		
Wood		2					
Vinyl Coil							
Interior Doors Type:					HOLLOW DOORS , DAMAGED		
Hollow Wood					FROM WATER, NEEDS REPLACED		
Solid Wood							

Interior Walls Type				_				WOC	DD FRAMED WALLS ALL	
Wood Frame				2				DAM	IAGED FROM MISSING	
Metal Frame								OUT	SIDE WALL S BEING GONE ,	
Sheetrock								FRO	M WEATHER DAMAGE WATER	
Stucco								ETC.		
Ceilings Type:				2					ER DAMAGED FROM ROOF LEAKS	
Sheetrock				2				,NEEL	OS REPLACED	
Stucco										
Ceiling Tile										
Flooring Underlay Type:			1					HOL	ES IN FLOORS THROUGHOUT	
1x6 center match								FRO	M WATER DAMAGE	
OSB										
Plywood										
Flooring Surfaces Type:								ALL	NEEDS TO BE REPLACED	
Carpet			1							
Linoleum										
Hard Wood										
Vinyl										
Electrical		1						NOT	TO CODE	
Heating		1				NOT TO CODE		TO CODE		
Plumbing		1						NOT TO CODE		
In my opinion, this structure		is	X	is not	Suitable for human habitation.					
In my opinion this structure		is	X	is not	Physically feasible for rehabilitation.					
In my opinion, this structure		is	X	is not	Economically feasible for rehabilitation.					
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.					
					•				-	
							ANTED			
H	OUS	E W	AS N	NOT SEC	JURE	U AT T	IME OF	INSPE	CTION	
Tim Renshaw, Chief Building	Inspe	ctor							Other Signature	
Tim Leno						_				
			_							
			+							
Municipal Bu	ilding	, 300	South	Church .	Jonesbo	oro, Ar./ l	Phone 870	-336-719	94/ Fax 870-336-1358	