

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	1-21-2019											
PROPERTY ADDRESS:	900 PATRICK											
PROPERTY OWNER:	CLEOPHUS & LOIS BRYANT											
OCCUPIED: YES NO X												
BUILDING ELEMENT	1	thru 5 (CONDIT	ION	NOTES & COMMENTS							
	VERY POOR			VER								
Foundation Type: Piers Solid			3		PART PIERS PART CONCRETE IN FAIR SHAPE							
Slab												
Front Porch Type: Wood Concrete			3		CONCRETE IN FAIR SHAPE							
Exterior Doors and Windows Type: Wood Vinyl Aluminum		2			MOST ARE MISSING AND ARE BOARDED UP ALLTHOUGH HOUSE WAS NOT SECURED AT TIME OF INSPECTION							
Roof Underlay Type: OSB/ Plywood 1x6 metal			3		MOSTLY PLYWOOD IN FAIR SHAPE							
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles			3		SHINGLES ARE OLD AND NEED REPLACED							
Chimney					N/A							
Siding Type: Wood Lap Vinyl Masonite Aluminum			3		BRICK SIDING COVERED IN GRAFFITI							
Fascia and Trim Type Wood Vinyl Coil		2			FASICIA AND TRIM NEEDS REPAIRED OR REPLACED , ROTTEN							
Interior Doors Type: Hollow Wood Solid Wood		2			ALL OFF HINGES AND NEED REPLACED							

Interior Walls Type								SHEE	ETROCK WALLS WITH HOLES		
Wood Frame				2				THR	OUGHOUT THE HOUSE ALL		
Metal Frame				2				NEEI	OS REPAIRED OR REPLACED		
Sheetrock											
Stucco											
Ceilings Type:								SHEE	ETROCK CEILINGS NEED		
Sheetrock					3			REPA	AIRED OR REPLACED		
Stucco											
Ceiling Tile											
Flooring Underlay Type:								PLYV	WOOD UNDERLAY NEEDS		
1x6 center match				2				REPA	AIRS IN SEVERAL AREAS		
OSB				2							
Plywood											
Flooring Surfaces Type:	•							ALL	FLOOR COVERING NEEDS		
Carpet			1					REPL	LACED		
Linoleum			1								
Hard Wood											
Vinyl											
Electrical								NOT	TO CODE		
Heating								NOT	TO CODE		
Plumbing								NOT	TO CODE		
<u>v</u>											
In my opinion, this structure		is	X	is not	Suit	able for	human ha	abitatio	n		
					Suitable for human habitation.						
In my opinion this structure		is	Х	is not	Physically feasible for rehabilitation.						
In my opinion, this structure		is	Х	is not	Economically feasible for rehabilitation.						
In my opinion, this structure	X	is		is not	A public safety hazard and should be condemned immediately.						
		0						N/EG			
							ANTED:				
H	UUS	ΕW	AS N	NOT SE(JURE	DAT T	IME OF]	INSPE			
Tim Renshaw, Chief Building							Other Signature				
Tim Rense											
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358											