

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	08						
PROPERTY ADDRESS:	82	-5 2	Bur Ke				
PROPERTY OWNER:	Joy		Mc Co.	mic	K		
OCCUPIED: YES	NO						
BUILDING ELEMENT			CON	DITIO	ON		NOTES & COMMENTS
		VERY				VERY	
Foundation	-	POOR	2	3	4	GOOD 5	- Home solling on STAKED Brit
Front Porch			2	3	4	5	A arts
Exterior Doors and Windows	ĺ	0	2	3	4	5	Roller Failing down
Roof Underlay		1	2	3	4	5	detecation
Roof Surface		<i>b</i>	2	3	4	5	Dut is showing stirtes
Chimney		1	2	3	4	5	-1d sugging & coming of
Siding		D	2	3	4	5	very weathered a metal used on Pr
Facia and Trim		0	2	3	4	5	Rotter & FAlling OFF
Interior Doors		1	2	3	4	5	N/A HOME -OWNER'S SON WOULD ST
Interior Walls		1	2	3	4	5	NA 1
Ceilings		1	2	3	4	5	aff "
Flooring Underlay		1	2	3	4	5	11
Flooring Surfaces		1	2	3	4	5	" //
Electrical		1	2	3	4	5	MAin Pur LAAD not ATTACHEN TO HEA
Heating		1	2	3	4	5	N/A could not gain Enty
Plumbing		1	2	3	4	5	11
In my opinion, this structure		is X	is not	suita	ble for	human h	abitation.
In my opinion this structure		is 🔀	is not	physically feasible for rehabilitation.			
In my opinion, this structure		is X	is not	economically feasible for rehabilitation.			
		•					
EMERGENCY CONDEMNATION IS WARRANTED: X YES NO							
In my opinion, this structure	X	is	is not	a pub	olic safe	ety hazai	d and should be condemned immediately.
/ 0 a1							
Tong & Holar	*			100			
Terry Adams, Certified Buildin	Craig Davenport, Fire Marshal Other S				al Other Signature		