

DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

					7			
DATE OF INSPECTION:	7-14-2014							
PROPERTY ADDRESS:	2713 Carria	ge Dr			Sera J Cook			
PROPERTY OWNER:	Jerry and A	pril Co	ok	2013 NO Power				
THOLERT OWNER	340-7519							
OCCUPIED: YES XX	NO							
BUILDING ELEMENT	1	thru 5 C	CONDIT	ION		NOTES & COMMENTS		
	VERY POOR				VERY GOOD			
Foundation Type:					5	Good Condition		
Piers								
Solid								
Slab								
Front Porch Type:					5	Concrete good condition		
Wood								
Concrete								
Exterior Doors and Windows				4		Fair condition but has issues		
Type:			- "-					
Wood								
Vinyl								
Aluminum		-	-			C1		
Roof Underlay Type:		2				Showing signs of dilapidation and		
OSB						leaking		
1x6								
metal		2	-			Charries sions of dilanidation and		
Roof Surface Type: Metal		2				Showing signs of dilapidation and leaking		
3-Tab Shingles						leaking		
Dimensional Shingles		-				N/A		
Chimney Siding Types		2	-			Rock infair condition/ Vinyl rotten and		
Siding Type: Wood Lap		1				dilapidated		
Vinyl/ Rock						diapidated		
Masonite								
Aluminum								
Fascia and Trim Type		2				Showing signs of dilapidation and rotten		
Wood						Sile wing signs of unaprunier and revers		
Vinyl Coil								
Interior Doors Type:	1	2	3	4	5	Could not access/ did look through		
Hollow Wood						windows for accessment		
Solid Wood								

Interior Walls Type		1		2					walls showing signs of			
Wood Frame/ Block								dilap	idation			
Metal Frame												
Sheetrock												
Stucco												
Ceilings Type:				2				Falli	ng in multiple issues			
Sheetrock												
Stucco												
Ceiling Tile												
Flooring Underlay Type:							5	Good	l condition			
1x6 center match												
OSB												
Plywood/ Concrete												
Flooring Surfaces Type:			1					Rotte	en showing signs of dilapidation			
Carpet												
Linoleum												
Hard Wood												
Vinyl												
Electrical			1				3.	Not t	o Code			
Heating		1						Not t	o Code			
Plumbing			1					Not t	o Code			
In my opinion, this structure		is	3/3/	is not	Cuital	bla for bu	man h	abitatio	20			
			XX	18 HOt	Suitable for human habitation.							
In my opinion this structure		is	XX	is not	Physically feasible for rehabilitation.							
In my opinion, this structure	XX	is		is not	Economically feasible for rehabilitation.							
In my opinion, this structure	XX	is	П	is not	A public safety hazard and should be condemned immediately.							
Due to Health, Safety and We	elafre	issu	es th	is structu								
EM	ERG	EN	CY A	CTION	IS WA	ARRANT	ED:	YE	S xx NO			
	-14-											
Terry Adams, Certified Building Inspector				Craig Davenport, Fire Marshal Other Signature								
Municipal Bu	ilding	300	South	Church	Jonesboi	ro, Ar./ Ph	one 870	-336-71	94/ Fax 870-336-1358			