




DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	3-6-17					
PROPERTY ADDRESS:	501 MARSHALL					
PROPERTY OWNER:	SHAUN WENDELL PARRISH					
OCCUPIED:	YES NO <input checked="" type="checkbox"/>					
BUILDING ELEMENT	1 thru 5 CONDITION					NOTES & COMMENTS
	VERY POOR				VERY GOOD	
Foundation Type: Piers Solid Slab						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Front Porch Type: Wood Concrete						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Exterior Doors and Windows Type: Wood Vinyl Aluminum						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Roof Underlay Type: OSB/ Plywood 1x6 metal						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Roof Surface Type: Metal 3-Tab Shingles Dimensional Shingles						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Chimney						
Siding Type: Wood Lap Vinyl Masonite Aluminum						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Fascia and Trim Type Wood Vinyl Coil						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Interior Doors Type: Hollow Wood Solid Wood						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED

Interior Walls Type Wood Frame Metal Frame Sheetrock Stucco						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Ceilings Type: Sheetrock Stucco Ceiling Tile						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Flooring Underlay Type: 1x6 center match OSB Plywood						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Flooring Surfaces Type: Carpet Linoleum Hard Wood Vinyl						HOUSE WAS DESTROYED BY FIRE, NEEDS TO BE REMOVED
Electrical						NOT TO CODE
Heating						NOT TO CODE
Plumbing						NOT TO CODE
In my opinion, this structure		is	<input checked="" type="checkbox"/>	is not		Suitable for human habitation.
In my opinion this structure		is	<input checked="" type="checkbox"/>	is not		Physically feasible for rehabilitation.
In my opinion, this structure		is	<input checked="" type="checkbox"/>	is not		Economically feasible for rehabilitation.
In my opinion, this structure	<input checked="" type="checkbox"/>	is		is not		A public safety hazard and should be condemned immediately.
EMERGENCY ACTION IS WARRANTED: YES <input checked="" type="checkbox"/> NO						
HOUSE WAS NOT SECURED AT TIME OF INSPECTION						
Tim Renshaw, Chief Building Inspector						Other Signature
						
Municipal Building, 300 South Church Jonesboro, Ar./ Phone 870-336-7194/ Fax 870-336-1358						