

## DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	10-22-08					
PROPERTY ADDRESS:	1014 S.	madi.	sod		c is ew	
PROPERTY OWNER:	MARGA	ret	BAK	er		
OCCUPIED: YES	NO					
BUILDING ELEMENT		CO	NDITION	V		NOTES & COMMENTS
	VERY POOR				VERY GOOD	
Foundation	<u>100k</u>	2	3	4	5	- Dealla / / Falling
Front Porch	Ď	2	3	4	5	Ratter
Exterior Doors and Windows	<b>(</b> )	2	3	4	5	Broke wood Frame's ROTTEN
Roof Underlay		2	3	4	5	Botter FAIling ;-
Roof Surface	(T)	2	3	4	5	11 11 11
Chimney	1		_3	4	5_	W/A
Siding	1	2	3	4	5	upod siding ROTTEN LETERIATE
Facia and Trim	1	2	3	4	5	ROTTEN FAILING OFF
Interior Doors	1	2	3	4	57	could not Access, fooked
Interior Walls	1	2	3	4	5	THEN WINDOWS, HAS WALL
Ceilings	1	2	3	4	5	danage & interior Trim
Flooring Underlay	1	2	3	4	5	dAm Age
Flooring Surfaces	1	2	3	4	5	
Electrical	(1)	2	3	4	5 (	All code issue's not up
Heating	<u>(1)</u>	2	3	4	5 5	to code's
Plumbing	(1)	2	3	4	5 (	
In my opinion, this structure	is X	is not	suitable for human habitation.  SAFELY & HEALTH physically feasible for rehabilitation.			
In my opinion this structure	is X	is not	physically feasible for rehabilitation.			
In my opinion, this structure	is	is not	economically feasible for rehabilitation.			
In my opinion, this structure	💢 is 🗌	is not	a public safety hazard and should be condemned.			
EMERGE	NCY CONDI	EMNAT	TON IS	WARI	RANT	ED: YES NO
In my opinion, this structure	is [	is not				d and should be condemned immediately.
Terry Adams, Certified Building	Craig	Craig Davenport, Fire Marshal			al Other Signature	