

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:		-76	08				9 90
PROPERTY ADDRESS:	13	509	PrA-	TT			
PROPERTY OWNER:	Bet	ty S.	n Ason				
OCCUPIED: YES	NO						
BUILDING ELEMENT			CON	DITIO	ON		NOTES & COMMENTS
22		VERY POOR				VERY GOOD	
Foundation	6. 5	1	62	3	4	5	Broke + Legain
Front Porch		1	(2)	3	4	5	Repla - concrete
Exterior Doors and Windows		1	0	3	4	5	Broke And Rotton
Roof Underlay		1	2	3	4	5	Fire HAS CAUSED LAMBON
Roof Surface		TO TO	2	3	4	5	Staing & Appears weak
Chimney		1	2	3	4	5	Broke Fire JAMAge
Siding		1	2	3	4	. 5	Aluminum
Facia and Trim		1	2	3	4	5	Buch't & ROTTEN
Interior Doors		1		3	4	5	FAIling OFF
Interior Walls		1	2	3	4	5	11 /1
Ceilings		O	2	3	4	5	ceilings FAlling in
Flooring Underlay		1	2	3	4	5	
Flooring Surfaces		1	2	3	4	5	could not Access
Electrical		1	2	3	4	5	
Heating		1	2	3	4	5	
Plumbing		1	2	3	4	5	V
In my opinion, this structure		is 📉	is not	suitable for human habitation.			
In my opinion this structure	П	is 🖂	is not	physically feasible for rehabilitation.			
· · · · · · · · · · · · · · · · · · ·	<u> </u>						
In my opinion, this structure		is 🔀	is not	economically feasible for rehabilitation.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO							
In my opinion, this structure	Ш	is 📙	is not	a pu	blic sa	tety hazar	d and should be condemned immediately.
Tent Hon	80						
Terry Adams, Certified Building Inspector				g Dave	enport,	Fire Marsh	al Other Signature