

AFFIDAVIT

| L & E PROPERTIES LLC | _ | |
|---|--|---|
| PO BOX 204 | _ | |
| STATE UNIVERSITY, AR 72467-0204 | _ | |
| | - | |
| RE: 202 W WOODROW | | |
| I, Michael McQuay, a Code Enforcement Officer, attached notice(s) upon each of the persons or firm thereof in the. United States Mail, enclosed within postage fully prepaid, at the Jonesboro, Arkansas I before 3:00 P.M., on the day of day of day | envelopes plainly addressed, by envelopes plainly addressed at 31 agust 20 | depositing copies essed, as shown with 0 East Street, Suite A 024 |
| | Michael McQ | uay Oy |
| | | de Enforcement |
| MY CO | ARIA RESENDEZ MMISSION # 00000932 RES: March 10, 2034 traighead County | , <u>2024</u> |
| Notary Public | - January | |
| • | | |

My commission expires: 10 March 2034



Notice of Violation

08/21/2024

L & E PROPERTIES LLC PO Box 204 State University AR 72467-0204

Case #: 240524

Subject: 202 W WOODROW, JONESBORO, AR 72401

Dear Property Owner:

According to county records you are the owner of the subject property. Please be advised that the structure on this property has been inspected by the City Building and Code Enforcement inspectors and, has been found to be unfit for human habitation by virtue of its dilapidated and unsanitary condition. This property poses a hazard to the public and is a nuisance against public health.

Within 10 (ten) calendar days from the date of this letter you are required to respond to this notice in writing, indicating you intention to either repair, re-inhabit, or raze and remove this structure. Should you choose to repair or rehab the structure, you will have to obtain a building permit and start work within 40 calendar days from the date of this notice. The building permit will be issued for a total of 45 calendar days at which time the repair or rehab work must be complete and able to pass all building, electrical, plumbing, and mechanical inspections.

If you decide to raze and remove this structure, removal and clean-up activities must be completed within 40 days of this notice.

If you decide not to repair or remove this structure, it will be necessary for the City Council to consider condemning the structure to ensure the repair, rehab, securing, and/or razing and removal of this nuisance. All costs involved in the condemnation process would be charged to you. Collection would be actively pursued.

We look forward to your cooperation in this matter. If you have any questions, call our office at (870)933-4658.

Cell: 870-926-1404 Email: dcooley@jonesboro.org

Sincerely,

David Cooley Code Enforcement Officer P.O. Box 1845

Jonesboro, AR 72403



DEPARTMENT OF INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

| DATE OF INSPECTION: | AUGUST 21, 2024 | CASE NUMBER: 240524 |
|---------------------|-----------------------|---------------------|
| PROPERTY ADDRESS: | 202 W. Woodrow St. | |
| PROPERTY OWNER: | L & E Properties, LLC | |

Building is a duplex apartment building. The residence is on a pier foundation. The perimeter of the foundation is in good shape. However, the piers on the interior foundation are breaking down and must be repaired or replaced. Due to the foundation starting to fail the interior floor is sagging. The floor in the bathroom and kitchen areas of both apartments is rotten and fallen in. There is standing water under the building. Some of the floor is so weak it is unsafe to walk on. Many of the floor joist must be replaced followed by most of the subfloor and flooring. The foundation issues are apparent on the roof as well. The lack of support from the foundation is causing the roof to start sagging. Once the foundation is repaired the roof must be closely inspected and any damage repaired. The soffit area of the home has wood that is starting to rot, pull away from the residence, and fall off. All damaged soffits must be repaired or replaced. All windows and doors have some sort of damage. Most of the windows have been broken out and door kicked in. All windows and doors must be repaired or replaced. Due to the damage inside the property he entire electrical system must be replaced, brought up to current code, and pass inspection. Due to the damage inside the property the entire plumbing system must be replaced, brought up to current code, and pass inspection. CURRENTLY THE BUILDING IS A HAZARD TO THE HEALTH, WELFARE, AND SAFETY OF THE PUBLIC. THE BUILDING SHOULD BE RAZED IMMEDIATELY TO ENSURE THE SAFETY OF LOCAL CHILDREN AND OTHER CITIZENS, NOT TO MENTION THE BLIGHT TO THE COMMUNITY. PROPERTY IS CURRENTLY SECURED BUT PREVIOUSLY WAS NOT SECURE ALLOWING THE INTERIOR TO BE INSPECTED.

| In my opinion, this structure | | Is | XX | Is not | Suitable for human habitation. |
|--|----|----|----|--------|---|
| In my opinion, this structure | | Is | XX | Is not | Physically feasible for rehabilitation. |
| In my opinion, this structure | | Is | XX | Is not | Economically feasible for rehabilitation. |
| In my opinion, this structure | XX | Is | | Is not | A public safety hazard and should be condemned immediately. |
| EMERGENCY ACTION IS WARRANTED: YES NO XX | | | | | |

| Tim Renshaw, Chief Building Inspector | David Cooley, Code Enforcement |
|---------------------------------------|--------------------------------|
| | |

Municipal Building, 300 South Church Jonesboro, AR/ Phone 870-336-7194/Fax 870-336-1358

U.S. Postal Service™ CERTIFIED MAIL® RECEIPT Domestic Mail Only For delivery information, visit our website at www.usps.com®. Certified Mail Fee Extra Services & Fees (check box, add fee Return Receipt (hardcopy) Return Receipt (electronic) Postmar Certified Mail Restricted Delivery Adult Signature Required Adult Signature Restricted Delivery \$ \$018 Postage Total Postage and Fees Sent To L & E Properties LLC Street and Apt. No., or PO Box No. PO Box 204 City, State, ZIP+4®

1988

1221

5270

0770

40

95

State University AR 72467-0204 PS Form 3800, January 2023 PSN 7530-02-000-9047 See Reverse for Instructions