

valure Hilson Cell 870-219-9331

DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	8-13-08	9		_		
PROPERTY ADDRESS:	103 E.	war d	,			
PROPERTY OWNER:	PATrick o	+ vAle	ri'e	Hils		
OCCUPIED: YES X	NO					
BUILDING ELEMENT		CONDITION			NOTES & COMMENTS	
	VERY POOR				VERY	
Foundation	1	2	3	4	GOOD 5	
Front Porch	1	2	3	4	5	acla
Exterior Doors and Windows		2	3	4	5	ROTTEN FAILING down
Roof Underlay	000	2	3	4	5	Ratter Hilling in
Roof Surface	D	2	3	4	5	Auther FAlling in
Chimney	1	2	3	4	5	M
Siding	1	2	3	4	5	Block up-11s
Facia and Trim	D	2	3	4	5	ROTEN
Interior Doors	1	2	3	4	5	NA
Interior Walls	1	2	3	4	5	NA
Ceilings	1	2	3	4	5	Soist All ROTTEN
Flooring Underlay	1	2	3	4	5	nff
Flooring Surfaces	1	2	3	4	5	NA
Electrical	9	2	3	4	5	ntring is poor condition
Heating	1	2	3	4	5	NHA no visible Heat Source
Plumbing	1	2	3	4	5	MA could not Tell if it is
In my opinion, this structure	is 🔀	is not	suitable for human habitation.			
In my opinion this structure	is 🔀	is not	physically feasible for rehabilitation.			
In my opinion, this structure	is 🔀	is not	economically feasible for rehabilitation.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO						
In my opinion, this structure is is not a public safety hazard and should be condemned immediately.						
Illy f- ffskam		5724 to 5				
Terry Adams, Certified Building Inspector Craig Davenport, Fire Marshal Other Signature						