

## DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	10-11-08				
PROPERTY ADDRESS:	PERTY ADDRESS: 1014 S.		SON		
PROPERTY OWNER:	MARGA	ret	BAKer		
OCCUPIED: YES X	NO				
BUILDING ELEMENT		CONDITION			NOTES & COMMENTS
	VERY POOR			VERY GOOD	и
Foundation	1)	2	3 4	5	Propos 4 FAlling out
Front Porch	(D)	2	3 4	5	RATTON
Exterior Doors and Windows	9990	2	3 4	5	Broke wood Framo's ROTTEN
Roof Underlay	0	2	3 4	5	Rotte - FAIling :-
Roof Surface	<b>©</b>	2	3 4	5	. 4
Chimney	1	2	3 4	5_	w/A
Siding	1	2	3 4	5	upod siding RUTTEN LETERATE
Facia and Trim	<b>(1</b> )	2	3 4	5	ROTTEN FAILING OFF
Interior Doors	1	2	3 4	5	could not Accoss, tooked
Interior Walls	1	2	3 4	5	THE WINDOWS, HAS WALL
Ceilings	1	2	3 4	5 >	danage & interior Trim
Flooring Underlay	1	2	3 4	5	dAm Age
Flooring Surfaces	1	2	3 4	5_/	,
Electrical	(1)	2	3 4	5 5	All code issues not up
Heating	<u>0</u>	2	3 4	5 5	to code's
Plumbing	(1)	2	3 4	5 (	
In my opinion, this structure	is 🔀	is not	suitable for human habitation.  SAFEIY & HEATTH  physically feasible for rehabilitation.		
In my opinion this structure	is 🔀	is not	physically feasible for rehabilitation.		
In my opinion, this structure	🔀 is 🗌	is not	economically feasible for rehabilitation.		
In my opinion, this structure	💢 is 🗌	is not	a public safety hazard and should be condemned.		
EMERGE	NCY CONDI	EMNAT	TON IS W	ARRANTI	ED: TYES TNO
In my opinion, this structure	is	is not			d and should be condemned immediately.
Terry Adams, Certified Building	Craig	g Davenport,	, Fire Marsha	d Other Signature	