

## DEPARTMENT OF PLANNING, INSPECTION AND CODE ENFORCEMENT

## RESIDENTIAL BUILDING INSPECTION REPORT

DATE OF INSPECTION:	9-	26-0	J				8
PROPERTY ADDRESS:	الم	W	- Fn	1257			2
PROPERTY OWNER:							<del></del>
PROPERTY OWNER:	W/11	liAM	LA	WerA	re	e_	And the second s
OCCUPIED: YES X	NO						
BUILDING ELEMENT			CONDITION			16	NOTES & COMMENTS
e		VERY POOR				VERY GOOD	
Foundation	<del></del>	(I)	2	3	4	5	COLLASIOP 2 FAllie
Front Porch	*	1	2	3	4	(5)	concrete
Exterior Doors and Windows		1	2	3	4	5	FAIR but need work
Roof Underlay		1	2	3	4	5	Rotting out
Roof Surface		1	2	3	4	5	WEATHORED 2 FAlling in
Chimney		1-		3 -	4_	5_	NA
Siding		1	2	3	4	. 5	FAIC Aluminum
Facia and Trim		1	2	3	4	5	FAIC
Interior Doors		(Ī)	2	3	4	5	
Interior Walls		1	2	3	4	5	All deteriated
Ceilings		(1)	2	3	4	5	And structure is
Flooring Underlay		(1)	2	3	4	5	collasping on sides
Flooring Surfaces		<b>(1)</b>	2	3	4	5	
Electrical		(1)	2	3	4	5	·
Heating		_	2	3	4	5	
Plumbing		1	2	3	4	5	
In my opinion, this structure		is 🛚	is not	suitable for human habitation.			
In my opinion this structure		is 💢	is not	physically feasible for rehabilitation.			
In my opinion, this structure		is X	is not	economically feasible for rehabilitation.			
EMERGENCY CONDEMNATION IS WARRANTED: YES NO							
In my opinion, this structure is is				a public safety hazard and should be condemned immediately.			
Lengt Ada	. 0						
Ferry Adams, Certified Building Inspector			Craig Davenport, Fire Marsha				al Other Signature